FORM F-2	2	OFFICER REPORT					
	Agenda Item Number	5.1	Item Title	Preside	nt		
	Date	07/21/23	Reported by	Travis A	Attanasio PE		
	Purpose	Summer 2022-23 I	Executive Comn	nittee Mee	eting		
OFFICER ACTIVIT	TIES						
 Attended the following ASCE conferences: ASCE Region 6 Student Symposium, Amarillo, TX April 12-16 ASCE Austin Branch Continuing Education Conference Austin, TX April 26 ASCE Offshore Technology Conference Dinner, Houston, TX May 1-2 ASCE Fort Worth Branch Meeting, Fort Worth, TX May 8 ACPA Mid-Year conference (Representing ASCE), Austin, TX June 6-7 ASCE International Conference on Transportation and Development and International Airfield and Highway Pavements Conference, Austin, TX June 14-15 ASCE Houston Branch Meeting, Houston, TX June 20 TPWA Conference (Representing ASCE), Waco, TX June 28-29 For the benefit of future Presidents, I have been tracking my hours spent on ASCE activities that are covered by my employer. It will hopefully provide future presidents a guide with which they can present to their managers or company leaders to ease any concern of getting paid work done. FY 2023 Q1 (10/1/22 – 12/30/22): 49.5 hours (Approximately 10% of total workable hours) FY 2023 Q3 (4/1/23 – 3/31/23): 79 hours (Approximately 16% of total workable hours) FY 2023 Q4 (7/1/23 – 9/30/23): 							
ITEMS FOR COM	MITTEE REPORTS						
alignme 2. Is any a	ent with the <u>Strategic</u> additional funding, b	<u>c Plan</u> .	t, required to co	mplete pla	leadlines. Discuss their anned programs/projects? adership?		
					1		
COMMITTEE	Branch/Section Rela	tions Committee (Sta	anding)	CHAIR	OPEN FOR 2022-23		
Preliminary talk	s have taken place	concerning the mergi	ng of 3 branche	es (Caproo	ck, West, High Plains)		
COMMITTEE	Office and Personne	el Committee (Standir	ng)	CHAIR	Travis Attanasio PE		
The OPC met on June 26 for a mid(ish) year update and to discuss personnel matters.							
COMMITTEEDiversity Equity & Inclusion (Standing)CHAIROPEN FOR 2022-23			OPEN FOR 2022-23				
Still seeking a Committee Chair							
COMMITTEE Past Presidents Council (Standing) CHAIR Susan Roth PE							
 The Texas Section Board at their April Board Meeting approved the Executive Committee's Endorsement of 2023 Texas OCEA Award & Award of Merit Recipients. OCEA: <u>Luce Bayou Interbasin Transfer Project</u> (Liberty and Harris Counties) Award of Merit: <u>Runway 13R-31L & Taxiway C Phase 1 Reconstruction Project</u> (City of Dallas) 							
ITEMS FOR AGEN	NDA List items rec	uiring action or discu	ussion here.				

FORM F-2	OFFICER REPORT								
	Agenda Item Number	5.2	Item Title	e Past President					
ASCE TEXAS SECTION	Date	07/21/23	Reported by	Patrick Beecher PE					
	Purpose	Summer 2022-202	3 Executive Co	mmittee N	leeting				
OFFICER ACTIVITIES									
 Participated in the Student Symposium meeting in Amarillo, Texas, as an attendee at the Texas Section Spring Board Meeting and manned a booth at the Career Fair for Terracon. Reached out to individuals in the Texas Section to encourage them to submit nominations for the Texas Section awards. Consulted with the Honors Committee on the process by which the committee will select the award winners. 									
ITEMS FOR COMMITTE	EE REPORTS								
alignment w 2. Is any addit	vith the <u>Strategic</u> ional funding, be	Plan.	t, required to co	mplete pla	leadlines. Discuss their anned programs/projects? adership?				
COMMITTEE	History & Heritage Committee (Standing) CHAIR			Melinda Luna PE					
 meeting will discuss the need for an owner of a landmark to write a letter of support. This will impact future dedication of landmarks. 2. Continued answering of questions. This quarter by the Texas Tribune and others. The Texas Tribune working on water infrastructure and its history. Questions were received on family members wanting to know the history of Hispanic women civil engineers. 3. Providing articles for Texas Civil Engineer magazine. 									
COMMITTEE	Honors Comm	ittee (Standing)		CHAIR	Stephen Crawford PE				
nominations Deadline fo The commit After all nor vote-getter Some addit o For o 5 n 4 th a reco on c o Juli to F	 ber 18, 2022 – Termination subset of a constraint of the second second	omittals was extended nominations total, in eccived, the Honors 7. 11 of the 14 Honor eritage Award catege 7 total) received the ote-getters were tied note that TexASCE highest vote-getter be ensure that the Te each year, we made parate winner for each n two options, included a second-place vote cond place vote-gett athleen Jackson for Committee member al Service Award to a	ed to May 15, 20 ocluding some w Committee con ors Committee n ory, there was c highest votes fo d, so we are rec guidelines state for the Professi xas Section rec e the decision to ch category. Jing Julie Jones e-getter to be so ters - Mahsa Ara the Service to F s voted, and the	23 tho were r apleted a members p nly 1 norr or the Life ommendin that 4 ca onal Servio ognizes th o have a s being sel elected for astoo for t eople Aw e results v	bership – online form for nominated multiple times round of voting for the top participated in this voting. nination for Anne Cook time Service Award and the ng that the top 5 nominees ndidates shall be awarded tice Award and for the Service ne greatest number of second round of voting so lected for one of these two r the other award. This the Professional Service rard vere to recommend the ce to People Award to				

Based on the nominations received and the final voting from the Honors Committee, we make the following recommendations for the 2023 Texas Section Awards:							
COMMITTEE	COMMITTEE Nominating Committee (Standing) CHAIR Lawrence Goldberg PE						
Nominating committee has held an election from June 1st to June 30th, 2023 for board positions. Below is the list of official nominees for election.							
President Elect (co Ron Reichert Mark Boyd	ntested) VP Technical Mark Mann						
VP EducationDirectors at Large (2)Genest LandryAdam EatonAngie Fealy							
VP Professional (contested) Julie Jones Steve Messina							
See Tellers report distributed onsite within the Director at Large report for election results.							
ITEMS FOR AGENDA	List items requiring action or discussion here.						
Item 4.2 – Accept and endorse recommendations for the 2023 Texas Section Awards							



INDIVIDUAL TEXAS SECTION HONORS AWARDS

Honors Committee Chair – Stephen Crawford PE,CFM Email: Crawford@Halff.com

Each year, the Texas Section presents awards to deserving individuals in the Section or in the community - nominated by their peers in recognition of their service. This is your opportunity to nominate a coworker, friend, or colleague you think deserves special recognition.

To submit a nomination, complete this form with a brief statement of the nominee's qualifications and return it by email to the Committee Chair listed above.

Nomination Deadline: May 15, 2023 The Awards Committee will review all nominations and present a list of candidates to the Board of Direction for selection. Awards are presented yearly at the Texas Civil Engineering Conference (CECON) unless otherwise indicated.

Texas Section Presidents, Past Presidents, Society-level officers, and past Society-level officers shall not be eligible to receive the Professional Service Award and/or the Professional Service to Students Award.

I would like to nominate

for the:

- AWARD OF HONOR: The Award of Honor was established by the Texas Section ASCE to be presented to a limited number of members of the Texas Section "in recognition of service to the Texas Section and outstanding professional achievement in civil engineering."
- PROFESSIONAL SERVICE AWARD: This award is conferred on a subscribing member of the Texas Section for meritorious service to the Texas Section and to one or more Section's Branches upon recommendations of the Honors Committee.
- HISTORY AND HERITAGE AWARD: This award is presented to an individual (not necessarily a member of the Texas Section) or Branch for making special contributions to recording and/or recognizing the history and heritage of civil engineering in Texas.
- SERVICE TO PEOPLE AWARD: This award is presented to a civil engineer (not necessarily a member of the Texas Section) who has distinguished himself or herself with special service to people. The award is intended to recognize civil engineers who bring credit to their profession through community activities that are visible to the general public.
- PROFESSIONAL SERVICE TO STUDENTS AWARD: This Award was established by the Texas Section Board of Directors in October 1999. It is conferred on a subscribing member of the Texas Section for meritorious service to the Texas Section through service to one or more of the Texas/Mexico Regional Conference's Student Chapters (Clubs).
 - GOVERNMENT CIVIL ENGINEER AWARD: This award is conferred on a subscribing member of the Texas Section employed by a governmental organization for meritorious service to the Texas Section and to one or more of the Section's Branches.
 - JOHN A. FOCHT, JR. CITIZEN ENGINEER AWARD: This Award was established by the Texas Section Board of Directors on October 11, 1990, to recognize John A. Focht, Jr.'s outstanding and continued dedication to the Texas Section of the American Society of Civil Engineers. Mr. Focht has served as Section Past President and Board Member, ASCE District Director, and Vice President and President of National ASCE. He originated the concept of encouraging members to become better citizen engineers.
- TEXAS SECTION ASCE LIFETIME SERVICE AWARD: The Texas Section ASCE Lifetime Service Award was established to honor enduring service and leadership to ASCE at the Texas, National, and Branch levels, generally to individuals in their mid-60s or later. This Award is presented on special occasions years. The last presentation was at the Texas Section Civil Engineering Conference in 2020.

Nominee — Name	Company	Company Telephone Number
Endorsements of Nominee-Name, Company Name and T	Felephone Number	
(1)		

(2)

*Please attach a brief (no more than one page) explanation of the candidate's qualifications for nomination.

NOTE: If you nominated someone last year who was not selected, you may re-nominate the individual(s).

CONTACT: Stephen Crawford PE.CFM EMAIL: sCrawford@Halff.com

A nomination may be submitted online at https://www.texasce.org/resources/history/awards-honors/2023-nominations/

e Jones Hors Committee voted 4 to 2 fi		Austin Dallas	95	Endorsements: Paul Hahn (Aguirre-Fields), Austin Messerli (K Friese)
e Jones Hors Committee voted 4 to 2 f	Nathan D. Maier	Dallas		
ors Committee voted 4 to 2 f			90	
ors Committee voted 4 to 2 f			90	
ors Committee voted 4 to 2 f			90	
	or Julie Jones to be selected for th	a Drofossional Consist A.		Endorsements: Nancy Cline (NSC Engineering), Allen M. "Bud" Beene (Parsons)
		e Projessional Service Av	vard	
	Public Utility Commission of			
		non-member		Nominator: Curtis Beitel (Walker Partners); Endorsements: Travis Attanasio, Susan Roth
ors Committee voted 4 to 2 f	or Kathleen Jackson to be selected	d for the Service to Peopl	e Award	
rk Mann	Sabine River Authority	Southeast Texas	83	Endorsements: Kate Osborn, Yassin Gallardo
Alvarez	Тхрот	Corpus Christi	97	Endorsements: Travis Attanasio (Texas Section President), Kimberly Cornett (Texas Section President-Elect)
	Fuerma Fuerina and			
		Heusten	00	Endorsements: Uttam Karmaker (Houston Branch President): Alexa Nichols (Houston Branch President-Elect)
icia Frayre	Consulting	Houston	60	Endorsements: Ottam Karmaker (Houston Branch President); Alexa Nichols (Houston Branch President-Elect)
e Cook	TYDOT	non-member	00	Endorsements: Melinda Luna (TRC), Allan Hayes
		non-member	33	Endorsements. Weimud Lund (MC), Andri Hayes
id Matocha	Rinker Materials	Austin	84	Endorsements: Paul Hahn (Aquirre-Fields), Tyler Dube (Pape Dawson)
				Endorsements: Alexa Nichols, Farrah Rawashdeh
				Endorsements: Nancy Cline (NSC Engineering), Ken Rainwater (retired)
				Endorsements: Nancy Cline (NSC Engineering), Martha Juch (TxDOT)
n M. "Bud" Beene			90	Endorsements: Nancy Cline (NSC Engineering), Susan Roth (Susan Roth Consulting)
	nleen Jackson ors Committee voted 4 to 2 f k Mann Alvarez icia Frayre e Cook id Matocha Newton tha Juch Rainwater	ors Committee voted 4 to 2 for Kathleen Jackson to be selected ik Mann Sabine River Authority Alvarez TxDOT icia Frayre Frayre Engineering and consulting Consulting e Cook TxDOT id Matocha Rinker Materials Newton Quiddity tha Juch TxDOT Rainwater Retired - Texas Tech	Inleen Jackson Texas non-member ors Committee voted 4 to 2 for Kathleen Jackson to be selected for the Service to People k Mann Sabine River Authority Southeast Texas k Mann Sabine River Authority Southeast Texas Alvarez TxDOT Corpus Christi icia Frayre Consulting Houston e Cook TxDOT non-member id Matocha Rinker Materials Austin Newton Quiddity Houston tha Juch TxDOT Austin Rainwater Retired - Texas Tech Caprock	Inleen Jackson Texas non-member 78 ors Committee voted 4 to 2 for Kathleen Jackson to be selected for the Service to People Award Award k Mann Sabine River Authority Southeast Texas 83 k Marez TxDOT Corpus Christi 97 k Marez Frayre Engineering and 88 88 consulting Houston 88 99 e Cook TxDOT non-member 99 idi Matocha Rinker Materials Austin 84 Newton Quiddity Houston 86 Hai Juch TxDOT Austin 86 Rainwater Retired - Texas Tech Caprock 84

FORM F-2 OFFICER REPORT Agenda 5.2						
Agenda - c						
Item Number 5.3 Item Title President Elect						
Date 07/21/23 Reported by Kimberly Cornett F	PE					
Purpose Summer 2022-2023 Executive Committee Meeting						
OFFICER ACTIVITIES						
- Planning of Leadership Development Weekend started since the last meeting and he	re we are.					
- TCE articles have continued, and planning of the next few months is ongoing.						
- CECON planning continues and moving along.						
- Met with strategic plan chair to create a plan for activities to complete.						
ITEMS FOR COMMITTEE REPORTS						
1. Provide the status of ongoing programs/projects with specific goals and deadlines. Discuss their						
alignment with the <u>Strategic Plan.</u>						
2. Is any additional funding, beyond current budget, required to complete planned progra3. Is there any additional information you would like to share with Section leadership?	ams/projects?					
John Mudd PE						
COMMITTEE Conference Planning Committee (Standing) CHAIRS Stephen Archer I	PE					
 Sponsorships/Exhibitors open since May 1, currently raised \$31K out of \$52K (Sponsorships) and \$43K out of 						
\$58K (Exhibitors). Many tabletop displays still available inside general meeting area.						
 Speaker/program tally has been finalized. Four Institutes are partnered w/ CECON and have established a full 						
program for each dedicated track room.						
 Poster sessions and lightning round presentations being finalized throughout the summer. STEM Program coming together to engage local (San Marcos) K-12 children to experience discipline-specific 						
 STEM Program coming together to engage local (San Marcos) K-12 children to experience discipline-specific presentation in a dedicated venue space 						
	II working through to					
 Keynote speakers for Wednesday and Thursday are secured. TxDOT Panel finalized; still working through to finalize Legislative (and panelist thus for) and Public Works Panels 						
finalize Legislative (one panelist thus far) and Public Works Panels.	 Technical tour shifted from CEMEX facility in New Braunfels to Concrete "3D Printed House" in Austin. 					

COMMITTEE	Editorial Committee (Standing)	CHAIR	Marita Moya PE			
 Recurring monthly meetings with the Directors at Large, President and President Elect, additional volunteer committee members, and Stephanie Ludlow to discuss TCE content. Utilizing updated article spreadsheet to enable more efficient tracking of content Supplying content for every other week TCE releases Continue to encourage social media engagement to promote TCE Coordinating with committee to improve outreach to universities to reach professors and graduate/research students to provide content to TCE Engage articles highlighting the Section Programs utilizing <i>Texas Civil Engineering</i> (TCE) Magazine Texas Civil Engineering Conference (CECON) (Promoting Fall 2023) ASCE Region 6 Student Symposium (Highlighting Spring 2023 Symposium) Legislative Drive-in (Highlighting Spring 2023 Drive-In) 						
COMMITTEE	Membership Committee (Standing)	CHAIR	Patrick Williams PE			
Meet virtually with each branch, individually, to discuss unique challenges (Summer 2023) Promote a 2023 Raffle/Sweepstakes for new members and promote Membership at at least (1) Conference as an Exhibitor (Summer 2023) Offer virtual Lunch-n-Learn RE: "The Benefits of ASCE Membership" to at least (1) Mega/Large company in Texas (Summer 2023)						

COMMITTEE	Strategic Planning Committee (Standing)	CHAIR	Angie Fealy PE			
 Met with President Elect Working on the one-page Strategic Plan Summary, similar to the update society did but we are more a summary of the new plan at this point. Create a summary sheet for the board and example of referencing the plan for meeting agendas, activities, and grant information. Recruit Incoming committee chair 						
ITEMS FOR AGE	ITEMS FOR AGENDA List items requiring action or discussion here.					
None						

FORM F-2		OFFICER REPORT					
	Agenda Item Number 5.4 Item Title		VP-Educational				
TEXAS SECTION	Date	07/21/23	Heather Guillen PE				
	Purpose	Summer 2022-2023 Executive Committee Meeting					

OFFICER ACTIVITIES

- 1. 2024 Region 6 Student Symposium monthly planning calls are ongoing.
- 2. 2025 Region 6 Student Symposium Kick-Off Meeting occurred in June 2023.

ITEMS FOR COMMITTEE REPORTS

- 1. Provide the status of ongoing programs/projects with specific goals and deadlines. Discuss their alignment with the <u>Strategic Plan</u>.
- 2. Is any additional funding, beyond current budget, required to complete planned programs/projects?
- 3. Is there any additional information you would like to share with Section leadership?

COMMITTEE	STEM Committee (T	ask)	CHAIR Carlos Martinez PE				
 Focus planning on CECON, working with Stephanie Ludlow. Schools are currently out for summer. Also supported our industry partner TAME with a \$1000 sponsorship and encouraged Section leaders to volunteer their time as a TAME student competition judge. No additional funding needed at this time. No additional information to share with Section leadership at this time. 							
COMMITTEE	Student Activities Committee (Standing) CHAIR Eva Schexnider EIT Student Activities Committee (Standing) Shannon Jungman PE						
 The Student Acitvities Committee is coordinating with Angelo State University for the 2024 Student Symposium event in San Angelo, Tx. The event is expected to take place in mid April at the on- campus Junell basketball center. Attendance and fundraising goals, and budget establishment are in progress. The committee has begun coordination with Tarleton State University for the 2025 event. Student planners have stated interest in co-hosting with new chapter Abilene Christian University. More info to come. There are several ASCE members who have expressed interest in volunteering with the SAC and have been included on invitations for the 2024 + 2025 symposium planning. Regular scheduled committee meetings will take place to establish monthly conference calls with students and bi-monthly calls with advisors. 							
COMMITTEE	Younger Members Committee (Standing) CHAIR Joe Alvarez						
ITEMS FOR AG	ENDA List items requ	uiring action or discussion here.	·	·			

FORM F-2		OFFICER REPORT			
	Agenda Item Number	5.5	Item Title	VP-Professional	
ASCE TEVAS SECTION	Date	07/21/23 Reported by Augustine Verrengia PE			
	Purpose	Summer 2022-2023 Executive Committee Meeting			

OFFICER ACTIVITIES

- 4/2023: Drafted the By-laws and implementation schedule for the creation of the Subject Matter Experts (SME) Committee
- 4/13/2023: Attended the ASCE Texas Section Spring board meeting.
- 4/21/2023: Attended the Government Affairs monthly meeting.
- 4/28/2023: Joined ASCE Texas Section members to deliver documents to Texas Legislators regarding supporting legislation around water infrastructure improvements.
- 5/4/2023: Attended the Beyond Storm Refresh meeting.
- 5/17/2023: Attended the ASCE Texas Section board 3rd Quarter leadership call.
- 5/17/2023: Attended the Beyond Storm refresh meeting.
- 6/16/2023: Attended the Government Affairs Committee meeting.

ITEMS FOR COMMITTEE REPORTS

- 1. Provide the status of ongoing programs/projects with specific goals and deadlines. Discuss their alignment with the <u>Strategic Plan.</u>
- 2. Is any additional funding, beyond current budget, required to complete planned programs/projects?
- 3. Is there any additional information you would like to share with Section leadership?

COMMITTEE	Governmental Affairs Committee (Standing)	CHAIR	Michael Bloom PE Sofia Carrillo EIT
-----------	---	-------	--

1. Status of Programs and Projects:

- (a) Legislative Drive In: Completed annual Legislative Drive-In event on April 3 and 4, 2023. Thirty-nine members attended. Completed meetings with 24 Texas Representatives and 15 Texas Senators. Earned \$10,500 in sponsorships and \$3,515 in registration fees for total revenue of \$14,015. Spent \$10,237 on venue costs. Earned \$3,778 in net revenue. Heard Senator Royce West, Texas 2036 policy expert, Kevin Longley from ASCE, and other speakers. Received favorable evaluation forms, with some wishing that handouts had been provided in advance and some asking for more time to schedule meetings with lawmakers. Published post-event article with photos in Section newsletter.
- (b) Follow Up Office Visits, Testimony, and Communications: Participated in Texas Water Infrastructure Coalition lobbying to secure additional state investment in water supply, wastewater systems, and flood mitigation. Visited lawmaker offices. Sent emails and letters to members involved in developing and passing the state budget. Testified at two budget hearings.
- (c) **CECON Legislative Panel:** Sent invites to lawmakers. Secured one confirmation so far Rep. Carrie Isaac.
- (d) **Branch GACs:** Working with branches to create local GACs. Current efforts focused on San Antonio (John Baker), Corpus Christi (Joe Alverez), and Dallas (Kimberly Cornet)
- 2. **Funding:** No additional funding is needed.

Additional Information to Share: Current Vice Chair Sofia Carrillo will be attending law school in the fall and a potential Vice Chair has been recommended. This individual will continue to serve during the legislature's "interim" period from Sept. 2023 to October 2024, with the intent to move into the Chair position after that period for the next active legislative year.

COMMITTEE	Texas Infrastructure (Standing)	Report Cards Committee	Co-CHAIRS	Griselda Gonzales PE Austin Messerli PE
 5/30/23 IRC Chair Training with National Currently coordinating the kick-off meeting Surveying previous IRC committee members on interest and location of meeting preference (virtual, in-person and location) Coordinating networking event at CECON IRC Volunteer QR code display at CECON (On ASCE table) 				
COMMITTEE	Beyond Storms Infra (Task)	astructure Network Resilience	CHAIR	Geoffrey Roberts
 The Committee is winding up the formal Refresh report to provide a detailed update on the progress made to the identified issues and changes required to address the problems uncovered by winter storms Uri and Viola. The report should be ready for realease in the next ~30 days. A refresh release webinar schedule for July 11 and we anticipate a further series of presentations to the public, industry, regulatory and legisaltive groups. 				
COMMITTEE	Flood Mitigation Adv	visory (Task)	CHAIR	Chad Ballard PE Lee von Gynz-Guethle PE
Discussing TWDB solicitation for feedback and comments. Communicating pubic opportunities to TxEWRI members.				
COMMITTEE	(Standing) Subcomms: Evaluation and Repair of	tions Oversight Committee Residential Foundations & Design - Manual of Practice	CHAIRS	Robert Pierry Jr. PE Ken Struzyk PE Phillip King PE
 Action on previous goals: Follow up with Riu Liu about the discussion of the Kalina and Lee paper we submitted. I did follow up, and Dr. Liu sent a letter to me indicating that they found our contribution valuable. He has contacted the authors for a response/closure, which they have until August 1st to submit. Our discussion and the authors' response will be published in the conference proceedings. Dr. Liu indicated that he needs a list of the contributing authors to be published with the discussion. I have drafted a letter to address this issue, which I intend to ask Jenni to review before I send it. Update Oversight Committee membership, including reconnecting with Lance Kinney, P.E. of the TBPELS. No action on this item this quarter. I plan to work on this within the next month or two. Other action: I was contacted by Augustine Verrengia, who asked that our Residential Foundations Committee respond to a letter from the Texas Association of Builders requesting feedback on their warranty and performance standards. This letter was sent to ASCE headquarters in Reston, Va., which put a very short time frame on providing a response. Fortunately, I already serve as an invited member of the TAB Change Review Group, which reviews their document every 2 years. I worked with Augustine, Travis, and Jenni to submit a response just prior to the June 2 deadline. Unfortunately, most of our proposed changes were not accepted. 				
ITEMS FOR AGE	NDA List items re	quiring action or discussion here.		
Item 3.3 - Vote for the creation of the Subject Matter Experts committee and continue discussions on the future of the Task Committees under VP Professional.				



5511 Parkcrest Drive, Suite 207 Austin, Texas 78731 (512) 472-8905 | TexASCE.org

June 1, 2023

Texas Association of Builders 313 East 12th Street, Suite 210 Austin, Texas 78701

Attention: Ned Munoz Vice President of Regulatory Affairs and General Counsel

Dear Ned:

On behalf of the American Society of Civil Engineers – Texas Section (ASCE Texas Section) we support the attached suggested edits to The Texas Association of Builders "Express Limited Home Warranty and Performance Standards". These suggested edits were developed by Robert F. ("Bob") Pierry, Jr., PE. As you know, Bob is a long-time member of the TAB Change Review Group. Bob is also Chair of the ASCE Texas Section Residential Foundations Oversight Committee.

Some history regarding the expertise of the ASCE Texas Section and the development of residential foundation guidelines is offered below:

The ASCE Texas Section adopted two guidelines for residential foundation engineering at the Fall 2002 Section Meeting. One was titled "Recommended Practice for the Design of Residential Foundations", and the other "Guidelines for the Evaluation and Repair of Residential Foundations" (ASCE Guidelines). The section began this work in 1999, mostly in response to a Policy Advisory issued by the Texas Board of Professional Engineers in 1998. Many ASCE practitioners believed that technical guidelines such as were included in the state's Policy Advisory should more rightly be created by a technical society such as ASCE. The State Board essentially rescinded the Policy Advisory pending the results of the ASCE effort, and copies of the ASCE Guidelines were presented to the State Board in January 2003. The 4-year initial development effort involved more than 47 ASCE members from across Texas. These documents have been updated with the latest version of "Recommended Practice for the Design of Residential Foundations" adopted in October 2007 and "Guidelines for the Evaluation and Repair of Residential Foundations Ver. 3" adopted in April 2022.

Further information about ASCE Texas Section efforts to develop and revise both documents is provided in a two-part series written by Bob and published in the Texas Civil Engineer magazine: Part 1 and Part 2

The ASCE Texas Section offers both documents at no cost via the Section website: <u>www.TexASCE.org</u>

Sincerely

Travis N. Attanasio PE, CFM ASCE Texas Section President 2023

Texas civil engineers are **leaders** in their **communities** building a **better quality of life** across the street and around the world.

PROMULGATED BY THE TEXAS ASSOCIATION OF BUILDERS (TAB) EXPRESS LIMITED HOME WARRANTY AND PERFORMANCE STANDARDS					
CONCERNING THE PROPERTY AT					
	(Street Address and City)				
Builder's Na Builder's Ade					
Builder's Pho Builder's Fax Builder's Em	(No.:				
§ 1. General	Provisions				
(a) Scope. This document describes the standards of performance for the various elements or components of a home as described. The Builder will repair or replace those elements or components of a home that do not meet thes standards during the applicable Warranty Period based upon the expected level of performance described in thes standards for residential construction to which the standards apply. If an element or component of a home is no described particularly herein, the element or component shall be constructed in accordance with the applicable writte agreement or, if there is no agreement, in accordance with the usual and customary industry standards or practice for similar Improvements (defined below) in the geographic region shall govern and the element or component sha perform for the purpose for which it is intended for the period of the applicable warranty. This document does no replace homeowner's insurance or any third-party warranty.					
(b) Definitions. The following words and terms when used in this warranty shall have the following meanings, unless th context clearly indicates otherwise.					
(1)	Adverse effectA tangible condition that substantially impairs the functionality of the habitable areas of the home.				
(2)	ASCE Guidelines"Guidelines for the Evaluation and Repair of Residential Foundations, Version 3", published by the Texas Section of the American Society of Civil Engineers (2022).				
(3)	Builder ResponsibilityA statement of the corrective action required by the Builder to repair the construction defect and any other damage resulting from making the required repair. Parties may agree to an alternative remedy.				
(4)	CodeThe International Residential Code or, if the context requires, the National Electrical Code.				
(5)	Construction Defect—a failure to meet the applicable performance standards as set forth herein of the home and subject to the provisions and procedures of the Residential Construction Liability Act, Chapter 27 of the Texas Property Code, except as modified by this Express Limited Home Warranty.				
(6)	Deflectionthe distorted shape of a structural element due to bending. Deflection is characterized by the deflection ratio.				

Page 1 of 33

09/01/2021

- (7) Deflection Ratio--the maximum deviation from a straight line between two points divided by the distance (L) between the two points.
- (8) Electrical Standard--for residential construction located in a municipality, a standard contained in the version of the National Electrical Code (NEC) applicable to electrical aspects of residential construction in the municipality under Local Government Code § 214.214 and that is effective on the date of commencement of construction of the home;
- (9) Excessive or Excessively--a quantity, amount or degree that exceeds that which is normal, usual or reasonable under the circumstance.
- (10) Exclusion--items, conditions or situations not warranted or not covered by a performance standard.
- (11) Extreme Weather Condition(s)--weather conditions in excess of or outside of the scope of the design criteria stated or assumed for the circumstance or locale in the Code.
- (12) Improvement(s)--any labor, materials, or other work supplied by Builder or its independent contractors or suppliers in performance of the contract documents or other written agreements, including, but not limited to, design plans or specifications.
- (13) The International Residential Code (IRC)--substantial compliance with the version of the IRC for One- and Two-Family Dwellings published by the International Code Council (ICC) as follows:
 - (A) for residential construction of the non-electrical standards of a One- and Two-Family Dwelling located in a municipality, the version of the IRC applicable to non-electrical aspects of residential construction in the municipality under Local Government Code § 214.212 and which is effective on the date of commencement of construction of the home;
 - (B) for residential construction of a One- and Two-Family Dwelling in the unincorporated area of a county, the most recent version of the International Residential Code published prior to the commencement of construction of the home, or the version of the IRC that is applicable in the county seat of that county, including any other applicable Codes required by statute.
- (14) Major Structural Components--the load-bearing portions, and the integral connection between them, of the following elements of a home: footings and foundations; beams; headers; girders; lintels; columns; load-bearing portions of walls and partitions; roof framing systems, to include ceiling framing; structural floor systems; and structural masonry arches. Major Structural Components do not include components and/or component parts such as, including but not limited to: non-load-bearing walls, non-load-bearing columns, wall tiles or wallpaper, drywall, plaster, flooring, subfloors and associated material, stucco of any kind or application, brick, stone, exterior siding, cladding, roof shingles, roof tiles, roof membranes, sheathing even if rated for structural support, tar paper, mechanical systems and its component parts, manufactured equipment, doors, trim, cabinets, hardware, insulation.
- (15) Manufactured Product--a component of the home that was manufactured away from the site of the home and that was installed in the home without significant modifications to the product as manufactured. Manufactured products commonly installed in residential construction include but are not limited to dishwashers, cook tops, ovens, refrigerators, trash compactors, microwave ovens, kitchen vent fans, central air conditioning coils and compressors, furnace heat exchangers, water heaters, carpet, windows, doors, light fixtures, fireplace inserts, pipes and electrical wires. For purposes of this warranty, a manufactured product includes any component of a home for which the manufacturer provides a warranty, provided that the manufacturer permits transfer of the warranty to the homeowner, any such transfer shall be without recourse against the Builder.

- (16) Original Construction Elevations--actual elevations of the foundation taken before, on or within 30 days of the Effective Date of Warranty of the residential construction project. Such actual elevations shall include elevations of porches and garages if those structures are part of a monolithic foundation. To establish original construction elevations, elevations shall be taken at a rate of at least one elevation per 100 square feet showing a reference point and shall be taken at a rate of at least one elevation per 10 linear feet along the perimeter of the foundation, subject to obstructions. Each elevation shall be taken on the surface of the foundation or on the surface of the floor covering on the foundation, if any. The type of floor finish or floor covering shall be identified for each elevation location or elevation grouping as applicable. For elevations surveyed on floor coverings, adjustments shall be made for the differential thickness between adjacent floor coverings such that all elevations reference a common plane. All intentional, as-built elevation changes, including but not limited to step-ups, step-downs, tire stops, sunken rooms, weather drops, and areas with drainage slopes shall be identified in location and magnitude. Original Construction Elevations shall be recorded with an accuracy of at least 1/8 of an inch (0.125 inch) on a to-scale plan view drawing of the home with interior and exterior walls to provide sufficient reference of each elevation location. If no such actual elevations are taken, the foundation for the habitable areas of the home are presumed to be level +/- 0.75 inch (three-quarters of an inch) over the entire area of the foundation.
- (17) Performance Standard(s)--the standard(s) to which a home or an element or component of a home constructed as a part of new home construction or a material improvement or interior renovation must perform.
- (18) Raised-Floor Foundation--a foundation comprised of a structural floor system that is elevated above the underlying ground surface by footings, piers, piles, or other localized foundation support elements. The foundation exhibits a void space or a crawlspace between the structural floor system and the underlying ground surface. Examples of raised floor foundations include, but are not limited to traditional wood floor systems, concrete slabs on metal formwork, and concrete slabs on temporary carton forms.
- (19) Slab-on-Ground Foundation--a foundation comprised of a concrete slab, either reinforced or post-tension, that is continuously supported by the underlying ground surface. The foundation may be a concrete slab of uniform thickness, or it may incorporate monolithic stiffening beams that are deeper than the slab sections. The foundation may be supplemented with piers; however, it is placed on, and directly supported by, the ground.
- (20) Span (L)--the distance between two supports for structural elements supported at both ends. For calculating overall deflection and/or tilt of foundations, L shall be defined as the edge-to-edge distance across the entire length of the foundation cross-section for which deflection or tilt is to be calculated. For calculating overall deflection and/or tilt of foundations, the minimum L shall be not less than 25 feet. Localized and/or shortened spans may not be used for calculations. For cantilevered framing elements, L shall be determined as twice the distance from the last support to the unsupported end of the element.
- (21) Substantial Completion--achieved when:
 - (A) the stage of construction when a new home, addition, improvement, or alteration to an existing home is sufficiently complete that the home, addition, improvement or alteration can be occupied or used for its intended purpose; or
 - (B) if required, the issuance of a final certificate of inspection or occupancy by the applicable governmental authority; or
 - (C) if no final inspection or certificate of occupancy is required, when all electrical, mechanical, and plumbing final inspections, or all other required inspections, if any, have been approved or all approvals for occupancy have been received from any applicable governmental authority; or

- (D) provided, however, that if Owner moves into, occupies and/or places personal property in the home or Improvements (or any portion of the property that is the subject of the contract), the home or Improvements shall be deemed to be for all purposes substantially completed.
- (22) Tilt --the planar rotation from a level condition to a slope across the entire foundation, edge-to-edge. Tilt is the mathematical difference in elevation of two points from opposing edges of a foundation divided by the distance (L) between the two points, expressed as a percent.
- (c) Additional Terms and Conditions
 - (1) Foreclosure. Notwithstanding any other term or condition herein, this Express Limited Home Warranty does not apply to Property and/or Improvements that have been subject to a foreclosure under Texas law, such Property and Improvements are taken "AS IS, with all faults."
 - (2) Commercial Purpose. Notwithstanding any other term or condition herein, this Express Limited Home Warranty does not apply to Property and/or Improvements that have been used at any time for a commercial, for profit, rental (short or long term), leasing or occupancy by any person other than the named owners on the deed recorded in the public records, such Property and Improvements are taken "AS IS, with all faults" and/or this Express Limited Home Warranty is cancelled upon the first or any use in violation of this provision.
 - (3) Green Building Compliance. Any and all green building requirements, standards, certifications or otherwise are controlled by those written standards applicable to and agreed upon between the Builder and the initial owner(s), if any, after which there is no warranty or guarantee related to or concerning any such green building requirements, standards, certifications or otherwise to any subsequent owner of the Property and/or Improvements. There is no guarantee or warranty for the energy efficiency, energy usage or otherwise of the home or Improvements in the Express Limited Home Warranty.
 - (4) Residential Construction Liability Act (RCLA) and Contractual Requirements. The contract associated with this Express Limited Home Warranty along with the terms and conditions therein are incorporated into this Express Limited Home Warranty, including but not limited to the dispute resolution provisions. As a condition precedent to the applicability of this Express Limited Home Warranty, the owner must follow each term and condition in the contract associated with this Express Limited Home Warranty, the requirements of the RCLA, all other legal requirements, and any and all other requirements in any instrument related to the Property and/or the Improvements, including but not limited to any third-party warranty. Any and all claims with the applicable third-party warranty company, insurance carrier or other responsible party is to be made before a claim under this Express Limited Home Warranty is presented to Builder, and there is no Builder Responsibility until same is fully completed in all respects unless Builder, at Builder's sole and exclusive discretion, agrees to participate concurrently.
 - (5) Approved Variations. Any variations in any element of construction, the Property and/or the Improvements that are not in compliance with the Performance Standard(s) or applicable Code(s) that are approved by an engineer associated with the project, included in the Construction Documents, provided for in the plans and specifications or approved by the local building official, governing authority, city inspector, third-party inspector or third-party warranty company are not warranted hereunder, are deemed within the Performance Standard(s) and are an Exclusion.
 - (6) Other Insurance or Warranty. This document does not replace homeowner's insurance or any third-party warranty. As a condition precedent to the applicability of this Express Limited Home Warranty, the owner must make a claim with the owner's homeowner's insurance carrier and third-party warranty company, as applicable. There is no Builder Responsibility for any loss paid, covered claim, repair or the like if same is available through

any insurance or third-party warranty. Any insurance or third-party warranty is primary and non-contributory to this Express Limited Home Warranty.

- (7) Access. In order to carry out the Builder Responsibilities, the Builder will require access to the home, the Property and Improvements. Builder and Builder designees shall be allowed full access in Builder's normal business operations for testing, inspection and repairs. Refusal or delay of more than ten calendar days upon verbal or written request of the Builder will waive and void any Builder Responsibility, unless mutually agreed upon in writing by the parties.
- (8) Non-Builder Repairs. Any and all repairs performed by any party without full compliance with this Express Limited Home Warranty waives any Builder Responsibility and any claim or cause of action against Builder related to same.
- (9) Resolving conflicts among construction standards. During the construction of the home, when an inconsistency exists between the Code, manufacturer's instructions and specifications, the standard required by the United States Department of Housing and Urban Development for Federal Housing Administration or Veterans Administration programs, or ANSI/ASHRAE Standard (62.2-2003), the most restrictive requirement shall apply if reasonable under the circumstances.
- (10) This Express Limited Home Warranty is fully transferable to subsequent homeowners without any additional paperwork or assignment. The subsequent homeowner's name must appear on the title filed in the deed records of the county for the subject property.
- (11) This Express Limited Home Warranty runs with the land and is a condition to any sale, transfer or otherwise related thereto. The terms and conditions of this Express Limited Home Warranty are incorporated by reference in and subsequent sale, transfer or otherwise regardless of any reference in the any such written instrument or document. Any and all subsequent homeowner is bound by the terms and conditions of this Express Limited Home Warranty. Any and all homeowners, now or in the future, accept this Express Limited Home Warranty by acceptance of title. To the extent that a subsequent homeowner has no knowledge of this instrument, actual or constructive, any assertion of a claim or cause of action against any person or entity that implicates the terms and conditions hereunder, the entirety of this document is applicable. This Express Limited Home Warranty cannot be changed or modified by any person or party whatsoever save and except for mutual written agreement between Builder and current homeowner.
- (12) Any claim or cause of action related to this Express Limited Home Warranty must be filed on or before the second anniversary plus one day of the date of discovery of the alleged construction defect; the statute of limitations for any such claim or cause of action is the second anniversary plus one day of the date of the discovery of the alleged construction defect; this provision does not extend the time period of any warranty.
- (13) HOMEOWNER AGREES AND UNDERSTANDS THAT OTHER THAN THE WARRANTIES PROVIDED IN THIS EXPRESS LIMITED HOME WARRANTY, ALL OTHER WARRANTIES ARE DISCLAIMED AND HOMEOWNER IS WAIVING ANY AND ALL EXPRESS AND IMPLIED WARRANTIES, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTY OF GOOD AND WORKMANLIKE REPAIR OR MODIFICATION OF EXISTING TANGIBLE GOODS OR PROPERTY, THE IMPLIED WARRANTY OF GOOD AND WORKMANLIKE CONSTRUCTION, PERFORMANCE, WORKMANSHIP, REPAIR, MODIFICATION, MERCHANTABILITY, SUITABILITY AND FITNESS. THE IMPLIED WARRANTY OF HABITABILITY IS WAIVED TO THE FULLEST EXTENT ALLOWED UNDER LAW, AS THE HOMEOWNER UNDERSTANDS AND AGREES THAT THE REPAIR OBLIGATIONS HEREUNDER ARE SUFFICIENT TO REPLACE ANY SUCH IMPLIED WARRANTY AND UNDERSTANDS THAT THE IMPROVEMENTS MAY BECOME UNSAFE FOR HABITATION BUT THAT THE OBLIGATIONS HEREUNDER ARE SUFFICIENT FOR THE REPLACEMENT OF ANY SUCH IMPLIED HABITABILITY WARRANTY; HOWEVER, TO THE EXTENT THAT IT IS FINALLY DETERMINED UNDER THE

Page 5 of 33

TAB A-14 ©

09/01/2021

DISPUTE RESOLUTION PROVISIONS HEREIN THAT THE IMPROVEMENTS ARE NOT HABITABLE DIRECTLY BECAUSE OF A CONSTRUCTION DEFECT, THE WARRANTY OBLIGATIONS HEREIN ARE SUFFICIENT TO CURE ANY SUCH CONSTRUCTION DEFECT TO BRING THE CONSTRUCTION DEFECT INTO COMPLIANCE WITH THE APPLICABLE STANDARD, NOTWITHSTANDING, THE BUILDER IS NOT LIABLE FOR ANY RESULTING DAMAGES, CONSEQUENTIAL DAMAGES, CONDITIONS, INJURIES, DEATH OR OTHERWISE. THE PARTIES AGREE THAT THE LIMITED WARRANTY ADEQUATELY SET FORTH THE MANNER, PERFORMANCE, AND QUALITY OF THE CONSTRUCTION OF THE IMPROVEMENTS. Homeowner acknowledges, understands, and agrees that the terms of this Express Limited Home Warranty are clear, specific, and sufficiently detailed to establish the only standards of construction performance. The Parties agree that this Express Limited Home Warranty will control any warranty, workmanship, material, or any other defect claims regarding the Improvements.

(14) The maximum warranty limit or warranty obligation hereunder is deemed the maximum obligation under any circumstance, including multiple claims, against this Express Limited Home Warranty and made in any manner against the Builder is the original, total purchase price in the original sales contract. Any obligation herein shall be deemed excess of any other insurance available, regardless of collectability and including any and all primary, umbrella or excess policies or coverages. Any other insurance available to any person or entity, including but not limited to the owner, third-party beneficiary, Builder, subcontractor or otherwise is primary and non-contributory to this Express Limited Home Warranty.

(15) **DISPUTE RESOLUTION; MEDIATION-BINDING ARBITRATION.**

The parties agree that any dispute or claim arising under, or relating to, this Warranty any amendments thereto, the Property, Improvements, or any dealings between the Homeowner and Builder or their representatives, shall first be submitted to mediation and, if not settled during mediation, shall thereafter be submitted to binding arbitration as provided by the Federal Arbitration Act (9 U.S.C. §§ 1 et seq.) or, if applicable, by similar state statute, and not by or in a court of law. All decisions respecting the arbitrability of any dispute shall be decided by the arbitrator. Any cost or fee associated with filing a claim for arbitration is to be paid by the party filing same. The Parties agree to split the mediation fee and the arbitrator's fees with all participating parties. The arbitrator has no authority to apportion to the prevailing party any portion of costs and fees. The mediation and, if necessary, the arbitration shall be conducted pursuant to the procedures set forth in any applicable Third-Party Warranty documents. If there is any conflict between this Warranty and the Third-Party Warranty on these procedures, the provisions of this Warranty shall control as to the Builder and Homeowner dispute or claims. Furthermore, if the mediator and/or arbitrator designated in any applicable warranty documents cannot conduct the mediation or arbitration for any reason, or if no mediator and/or arbitrator is designated, the parties agree to work together in good faith to select a mediator. If the parties are unable to agree on the appointment of a mediator and/or arbitrator, then the mediation and arbitration shall be conducted by DeMars & Associates (DeMars) or the American Arbitration Association (AAA), in accordance with the applicable rules and procedures provided by such service providers; however, if there is any conflict between this Warranty and such rules or procedures, the provisions of this Warranty shall control. The choice of AAA or DeMars shall be the choice of the party that first files for mediation and/or arbitration respectively, and one service may be used for mediation and another for arbitration. In the event that the dispute or claim involves only construction defect claims under the Residential Construction Liability Act and no other dispute, claim or cause of action is asserted and if an in-person, evidentiary hearing is not necessary then, at Builder's election, Builder may submit or transfer all of the disputes and claims to Construction Dispute Resolution Services (CDRS). If for any reason the AAA, DeMars and CDRS is unable or unwilling to conduct the mediation or the binding arbitration, or both, either party may petition a court of general jurisdiction in the subject county to appoint a mediator or arbitrator, or

both, but only after a good faith effort to agree to an alternative mediator, arbitrator or service provider. It is agreed that the filing of a petition requesting appointment of a mediator or arbitrator, or for a court to resolve a dispute under this provision, shall not constitute a waiver of the right to enforce binding arbitration.

In any arbitration proceeding between the parties the following material terms shall apply:

- (A) The arbitrator shall have no authority to award any remedy or damage not provided by this Contract, Federal law or State law;
- (B) All applicable claims, causes of action, remedies, and defenses as available in court shall apply, including temporary and permanent restraining orders;
- (C) The proceeding shall be conducted by a single arbitrator selected by a process designed to ensure the neutrality of the arbitrator;
- (D) Subject to relevance and discovery reasonably calculated to lead to the discovery of admissible evidence, proper objections, confidentiality and other privileges, the parties shall voluntarily produce documents related to the claims and disputes, and the parties shall be entitled to conduct reasonable and necessary discovery as limited by the arbitrator but in no event shall any party be entitled to more than 6 hours of total deposition time, 10 requests for production and disclosures under Tex. Rule of Civ. Pro. 194; no interrogatories shall be allowed;
- (E) The arbitrator shall render a written award and, if requested by any party at any time, a reasoned award, even if after the written award is issued;
- (F) No party shall be required to pay any unreasonable costs, expenses, or arbitrator's fees;
- (G) Judgment upon any such award may be entered in any court having jurisdiction, subject to the terms and conditions herein and the Federal Arbitration Act;
- (H) If the proceeding pertains to a construction defect, as that term is defined in Chapter 27 of the Texas Property Code (§27.001(4)), then the arbitration shall be conducted in the same county as the Property, absent agreement of the parties or the arbitrator's determination that such location is inconvenient;
- (I) Any arbitration shall be private and confidential, and no publication or disclosure of such arbitration or facts surrounding same shall be made to any third-party, except for necessary testimonial witnesses, experts and counsel. The final award of the arbitrator shall not be payable until 60 days after such award, and such award shall not be sought to be confirmed in any court until 90 days after such award, with or without objection by any party and regardless of the terms and conditions of the award. If the award requires repairs of construction defects, such repairs are not required to be commenced until 90 days after the award is confirmed but shall be completed within 120 days after the award is finally confirmed.

Homeowner and Builder agree that notwithstanding anything to the contrary, the rights and obligations set forth in this mediation-arbitration agreement shall survive (1) the termination of this Contract by either party; and/or (2) the breach of this Warranty by either party. The waiver or invalidity of any portion of this mediation-arbitration agreement shall not affect the validity or enforceability of the remaining portions of this mediation-arbitration agreement and/or the Warranty Homeowner and Builder further agree (1) that any dispute involving Builder's directors, officers, partners, employees and agents shall be resolved as set forth herein and not in a court of law; and (2) that Builder shall have the option to include its subcontractors, suppliers, and vendors as parties in the alternative dispute resolution procedures set forth in this Warranty.

This Warranty requires mandatory mediation and arbitration of all claims and disputes; if any party commences litigation in violation of this Warranty, that party shall reimburse the other parties for all costs and expenses including attorneys' fees incurred in seeking abatement of such litigation and enforcement of mediation and/or arbitration.

Homeowner and Builder expressly agree that this Warranty is being entered into for the benefit of any third-party and/or subsequent owner that owns, inhabits or resides in the Improvements, Property or dwelling and is therefore subject to this requirement to arbitrate any and all claims concerning this Contract, the Property, Improvements or dwelling.

Homeowner further agrees that if Homeowner sells the Property and Improvements, Homeowner agrees to inform the subsequent purchaser(s) of this requirement to arbitrate in accordance with this Contract and, as part of any sales agreement, agrees to require the subsequent purchaser(s) to arbitrate any and all claims that may arise between Homeowner, Builder or subsequent purchaser(s) relating to or arising under, in whole or in part, to this Contract, the Property or Improvements.

- (16) A request for warranty performance is not to be construed as a notice of construction defect under the Texas Residential Construction Liability Act and that any notice under said action shall be separately sent as required herein and under law.
- (17) Any dispute, claim and/or cause of action must be filed for arbitration no later than two years and one day after the date of accrual and the statute of limitations is shortened to this time period unless any such Dispute, claim and/or cause of action already has a shorter limitations period as a matter of law. It being a breach of contract and violation of this Express Limited Home Warranty, the filing of a lawsuit in a court of law does not toll the limitations periods.
- (18) Under no circumstances shall a party be liable for any special, indirect, or consequential damages, including claims of mental anguish.
- (19) This Express Limited Home Warranty is not governed by the Texas Real Estate Commission.
- (20) THE PARTIES HERETO HEREBY WAIVE THEIR RESPECTIVE RIGHTS TO A JURY TRIAL OF ANY DISPUTE, CLAIM OR CAUSE OF ACTION.
- § 2. General Provisions for New Homes, Material Improvements and Interior Renovations
 - (a) Builder Responsibilities for Compliance with Performance Standards and Repair Obligations.
 - (1) Builder's Work. The Builder is responsible for all work performed under the direction of the Builder for the period of the applicable warranty. The Builder is only responsible for construction defects about which the Builder receives written notice in compliance with Sec. 1(c)(4) no later than thirty (30) days following the expiration of the applicable warranty period:
 - (A) the date of the initial transfer of title from the Builder to the initial owner of the affected home or improvement; or
 - (B) if the transaction that is the subject of the dispute did not involve a title transfer, the date that the construction was substantially complete unless otherwise expressly stated herein.
 - (2) Repair Obligations. Unless otherwise stated under the various performance standards herein, if any such performance standard is not met, the Builder shall take such action as is necessary to bring the variance within the standard, subject to the terms and conditions herein. The method and manner of any repair is within the sole discretion of Builder. The Builder shall have the option in its sole and exclusive discretion to repair, replace or pay for the reasonable cost of repair of any construction defect or exercise any remedy available to it under law

or contract, or any combination of any of the preceding. As a condition precedent to any obligation herein, the homeowner must make a written, unconditional assignment to the Builder or its designee any and all rights, remedies or otherwise that the homeowner has or may have against any other entity, person or third-party of or relating to the subject property, Improvements or otherwise. If the homeowner or any of homeowner's agents, representatives or affiliates have assigned or otherwise prejudiced any rights related this Express Limited Home Warranty or the subject property or Improvements, the obligations hereunder are waived to any such extent of said assignment or prejudice. The Builder retains all rights of subrogation, which shall not be assigned or waived by the homeowner. Builder has the unrestricted right to subrogation against any and all third-parties, including but not limited to any person or entity constructing, modifying, supplying materials, labor or otherwise to the Improvements, insuring the Improvements, or in any way causing Builder to incur or accept liability, damages or the like hereunder. Upon selection by Builder of the one or more options herein, the homeowner shall execute a recordable release of all claims and causes of action related to the construction defects, any condition and/or damages related to the construction defect, and this Express Limited Home Warranty to the extent of the construction defects, save and except that any remaining Warranty Period or express obligation hereunder shall not be released. No repairs performed by or on behalf of Builder shall extend the Warranty Period or any other obligation hereunder.

- (3) Repair Condition. In connection with a repair of a construction defect, any repairs performed by the Builder will include those components of the home that have to be removed or altered in order to repair the construction defect. Repair shall be made so that the condition is returned to its condition as it existed at the time immediately preceding the construction defect. Any repair will be finished or touched up to match the surrounding area as closely as practical but not necessarily to a like-new condition. Imperfections and variations may exist and should be expected. A repair or action bringing a variance within the standard under this warranty shall not cause the period of the applicable warranty to be extended.
- (4) Finish. Surfaces altered incident to any repair will be finished or touched up to match the surrounding area as closely as practical but not necessarily to a like-new condition. Imperfections and variations may exist and should be expected. In connection with the repair of finish or surface material, such as paint, wallpaper, flooring or a hard surface, the Builder will match the standard and grade as closely as reasonably possible. Builder will attempt to match the finish but will not be responsible for discontinued patterns or materials, color variations or shade variations. When the surface finish material must be replaced and the original material has been discontinued, the Builder is responsible for installing replacement material substantially similar in appearance to the original material.
- (5) Manufactured Products. The Builder shall install all manufactured products in accordance with the manufacturer's instructions and specifications.
 - (A) The Builder shall use only new manufactured products and parts unless otherwise agreed in writing by the parties. If the Builder did not install a manufactured product in accordance with the manufacturer's specifications or use newly manufactured parts as required, the Builder shall take such action as is necessary to bring the variance within the standard.
 - (B) The homeowner shall notify the Builder in writing of a known construction defect not later than the second anniversary of the date of discovery of the construction defect or not later than thirty days following the applicable warranty period. In no event shall there be Builder Responsibility for any Manufactured Product that was installed in accordance with the manufacturer's instructions and specifications. In no event shall there be Builder Responsibility for any denial of warranty claim or otherwise by the manufacturer.
- (6) Specialty Feature. Notwithstanding a performance standard stated in this Express Home Warranty, a specialty feature, which is work performed or material supplied incident to certain design elements shown on the

construction plans and specifications and agreed to in writing by the Builder and the homeowner, shall be deemed to be compliant with the performance standards stated herein so long as all items are compliant with the Code.

- (b) Exceptions and Exclusions from Builder's Responsibilities.
 - (1) The Builder is not responsible for repair, loss or damage to a component or that part of a component of a home caused by or made worse by any of the following:
 - (A) Work performed or material supplied incident to construction, modification or repair to the home performed by anyone other than the Builder or persons providing work or material at the direction of the Builder.
 - (B) The negligence, improper maintenance, misuse, abuse, failure to follow manufacturer's recommendations, failure to take reasonable action to mitigate damage, failure to take reasonable action to maintain the residence or other action or inaction of anyone other than the Builder or persons providing work or material at the direction of the Builder.
 - (C) Failure of the homeowner to comply with the homeowner's responsibilities as set forth in subsection (c) of this section or as may be stated separately elsewhere in this warranty.
 - (D) Alterations to, or the failure to maintain, the grade of the soil that are not in compliance with the Code, applicable governmental regulations or in compliance with an applicable drainage plan.
 - (E) Normal wear and tear or normal deterioration to any component of the home.
 - (F) Extreme weather conditions.
 - (G) Riot, civil commotion, war, terrorism, vandalism, aircraft, vehicle or boat.
 - (H) Fire, smoke or water damage unless such loss or damage is a direct result of a construction defect.
 - (I) Change in the underground water table that exerts pressure on, seeps, or leaks under the home, sidewalk, driveway, foundation or other structure or causes subsidence or sinkholes.
 - (J) Erosion or accretion of soils unless such loss or damage is a direct result of a construction defect.
 - (K) Insects, birds, rodents, vermin or other wild or domestic animals unless such loss or damage is a direct result of a construction defect.
 - (L) The quality and potability of water unless caused by a construction defect.
 - (M) While the home is being used primarily for nonresidential purposes.
 - (N) Use for which the home or the component of the home was not designed.
 - (O) Use that exceeds the normal design loads prescribed by the Code or the engineer of record.
 - (P) Homeowner delay in reporting a known construction defect or failing to take reasonable action necessary to prevent further damage to the home.
 - (Q) For remodeling projects, improvements, alterations or additions to an existing residence where the performance standard cannot be achieved due to an existing condition.
 - (R) Abuse or misuse of a home component or manufactured product by anyone other than the Builder or persons providing work or material at the direction of the Builder.
 - (S) Failure and/or violation to meet applicable Code by itself for any element of construction or construction technique for the Property and/or Improvements is not negligence per se, breach of contract or breach of

warranty and does not create a cause of action or Builder Responsibility. A claim or allegation that there is a failure to meet or violation of Code must be accompanied by both (1) actual physical resulting damage from that failure or violation of Code to the Property or Improvements and (2) an immediate threat to the health and safety for the occupants or invitees. There is no Builder Responsibility to repair any failure to meet Code or violation of Code that would result in economic waste.

- (T) Under no circumstance is any landscaping, whether currently existing trees, plants, or grass on the subject property, or any of those installed by Builder, warranted by this Express Limited Warranty.
- (2) No Actual Physical Damage. The Builder shall not be responsible for any condition that does not result in actual physical damage to the home, including, but not limited to the presence of radon gas, formaldehyde or other pollutants or contaminants, or the presence or effect of mold, mildew, toxic material, or volatile organic compound, unless such condition is a direct result of a construction defect.
- (c) Homeowner's Responsibilities.
 - (1) Home Maintenance. Maintenance of the home and the lot on which the home is located are essential to the proper functioning of the home. The homeowner is responsible for maintenance of the home and the lot on which it is located and any contiguous property owned or controlled by the homeowner. The homeowner is responsible for maintenance items described in this paragraph and those maintenance items identified separately in the performance standards set forth in this warranty. Additionally, the homeowner is responsible for ongoing maintenance responsibilities that affect the performance of the home but that may not be expressly stated in this warranty. Such ongoing maintenance responsibilities include, but are not limited to, periodic repainting and resealing of finished surfaces as necessary, caulking for the life of the home, regular maintenance of mechanical systems, regular replacement of HVAC filters, cleaning and proper preservation of grading around the home and drainage systems to allow for the proper drainage of water away from the home.
 - (2) Manufactured Products. The homeowner shall use and perform periodic maintenance on all manufactured products according to the manufacturer's instructions and specifications. The misuse, abuse, neglect or other failure to follow manufacturer's specifications with regard to manufactured products may void the manufacturer's warranty. The Builder has no Builder Responsibility for Manufactured Products.
 - (3) Landscape Planting. The homeowner shall take measures to prevent landscaping materials or plants from contacting the exterior surface of the home and from interfering with the proper drainage of water away from the foundation. The homeowner should not improperly alter the proper drainage pattern or grade of the soil within ten feet of the foundation so that it negatively impacts the home's performance or fails to comply with the Code, governmental regulations or an applicable grading and drainage plan. There is no warranty for landscaping, plants, trees, grass or other plant materials.
 - (4) Subsequent Improvements. The homeowner shall take measures to prevent subsequent improvements, including but not limited to additions, patios, arbors, pools, and retaining walls from interfering with the proper drainage of water away from the foundation. The homeowner should not alter the proper drainage pattern or grade of the soil within ten feet of the foundation so that it negatively impacts the home's performance or fails to comply with the Code, governmental regulations or an applicable grading and drainage plan.
 - (5) Humidity or Dryness in the Home. The homeowner should take the following actions to prevent excessive moisture accumulation by:
 - (A) properly using ventilation equipment;
 - (B) preventing excessive temperature fluctuation; and

- (C) taking any other action reasonably necessary to avoid excessive moisture, dampness, humidity or condensation in the home that may lead to damage due to excessive moisture or dryness.
- (6) Proper Maintenance and Care of Home Components. The homeowner shall properly maintain each component of the home including proper cleaning, care and upkeep of the home. The homeowner shall use home components for the purposes for which they are intended and shall not damage, misuse or abuse home components.
- (7) Self-Help. Upon observation of a circumstance that may cause further damage to the home or a component of the home, the homeowner shall take reasonable action necessary to prevent further damage.
- § 3. Express Limited Home Warranty
 - (a) Warranty periods. The warranty periods for residential construction and residential improvements are:
 - (1) one year for workmanship and materials;
 - (2) two years for plumbing, electrical, heating, and air-conditioning delivery systems; and
 - (3) ten years for major structural components of the home.
 - (b) Manufactured Product Warranties. The Builder will assign to the homeowner, without recourse, the manufacturer's warranty for all manufactured products that are covered by a manufacturer's warranty. Any rights that inure to the homeowner provided under a manufacturer's warranty are the obligation of the manufacturer. The Builder does not assume any of the obligations of the manufacturer resulting from a manufacturer's warranty, but shall coordinate with the manufacturer, suppliers or agents to achieve compliance with the performance standard. If the manufacturer does not comply with the manufacturer's warranty within a reasonable period of time, the Builder will make the affected condition comply with the performance standard and seek redress from the manufacturer.
 - (c) Cosmetics, Workmanship and Materials Warranty and Performance Standards. Workmanship and materials in residential construction or residential improvements are warranted to perform to the performance standards that are set forth in this warranty for the minimum period established in subsection (a) paragraph (1) of this section, unless a greater period of warranty is agreed to by the parties.
 - (d) Delivery Systems Warranty and Performance Standards. Plumbing, electrical, heating and air-conditioning delivery systems in residential construction and residential improvements shall be warranted to perform to the performance standards that are set forth in this warranty for the minimum period established in subsection (a) paragraph (2) of this section, unless a greater period of warranty is agreed to by the parties.
 - (e) Structural Components Warranty and Performance Standards. Major structural components in residential construction and residential improvements shall be warranted to perform to the performance standards set forth herein for the minimum period established in subsection (a) paragraph (3) of this section, unless a greater period of warranty is agreed to by the parties.
 - (f) Effective Date of Warranties.
 - (1) Unless otherwise provided by a written agreement between the Builder and the initial homeowner or by a manufacturer, a warranty period as described in this section for a new home begins on the earlier of the date of occupancy or transfer of title from the Builder to the initial homeowner.
 - (2) A warranty period as described in this section for an improvement other than a new home or for a partially built home, which by agreement between the homeowner and the Builder, someone other than the Builder will

complete, begins on the date the improvement is substantially completed or the terms of the construction contract are substantially fulfilled.

ONE YEAR WARRANTY PERIOD

- § 4. Performance Standards for Yard Grading
 - (a) Yards shall have grades, swales and/or other measures that provide for proper drainage in accordance with the Code, governmental regulations or otherwise in accordance with an applicable drainage and grading plan, if any, and/or approved variations. The homeowner shall maintain the drainage pattern and protect the grading contours from erosion, blockage, over-saturation or any other changes. The possibility of standing water, not immediately adjacent to the foundation but in the yard, after prolonged or an unusually heavy rainfall event should be anticipated by the homeowner.
 - (b) Settling or sinking of soil shall not interfere with the drainage patterns of the lot or have a vertical depth of six inches or more.
- § 5. Performance Standards for Foundations and Slabs
 - (a) Performance Standards for Raised Floor Foundations or Crawl Spaces.
 - (1) A crawl space shall be graded and drained properly to prevent surface run-off from accumulating deeper than two inches in areas 36 inches or larger in diameter. Exterior drainage around perimeter of a crawl space shall not allow water to accumulate within ten feet of the foundation for more than 24 hours after a rain except in a sump that drains other areas. Water shall not enter into the basement or crawl space or seep through the basement floor. The homeowner shall not modify improperly the existing grade or allow water from an irrigation system to cause water to accumulate excessively under the foundation. The homeowner shall not allow landscape plantings to interfere with proper drainage away from the foundation. The homeowner shall not use the crawl space for storage of any kind.
 - (2) The homeowner shall not modify improperly the existing grade or allow water from an irrigation system to cause water to accumulate excessively near the foundation. The homeowner shall not allow landscape plantings to interfere with proper drainage away from the foundation.
 - (b) Performance Standards for Concrete Slab Foundations, excluding Finished Concrete Floors.
 - (1) Concrete floor slabs in living spaces that are not otherwise designed with a slope for drainage, such as a laundry room, shall not have excessive pits, humps, depressions or unevenness equal to or exceeding 3/8 of an inch in any 32 inches and shall not have separations or cracks that equal or exceed 1/8 of an inch in width or 1/16 of an inch in vertical displacement.
 - (2) Concrete slabs shall not have protruding objects, such as a nail, rebar or wire mesh.
 - (3) Concrete portions of a raised-floor foundation should not have separations or cracks that equal or exceed 1/8 of an inch in width or 1/16 of an inch in vertical displacement.
 - (4) A separation in an expansion joint in a concrete slab of a raised-floor foundation shall not equal or exceed 1/4 of an inch vertically or one inch horizontally from an adjoining section.

- (5) Slab-on-ground foundations should not have separations or cracks that equal or exceed 1/8 of an inch in with or 1/16 of an inch in vertical displacement.
- (6) A separation in an expansion joint in a concrete slab shall not equal or exceed 1/4 of an inch vertically or one inch horizontally from an adjoining section.
- (c) Performance Standards for Exterior Concrete including Patios, Stem Walls, Driveways, Stairs or Walkways.
 - (1) Concrete corners or edges shall not be damaged excessively due to construction activities.
 - (2) Exterior concrete shall not contain a protruding object, such as a nail, rebar or wire mesh.
 - (3) The finish on exterior concrete shall not be excessively smooth, so that the surface becomes slippery. A concrete surface that has been designed to be smooth is excepted from this performance standard.
 - (4) A driveway will not have a negative slope unless due to site conditions, it has swales or drains properly installed to prevent water from entering into a garage. If a driveway is sloped such that it allows water to enter a garage in normal weather conditions, the Builder shall take such action as is necessary to prevent water from entering the garage due to driveway slope.
 - (5) Concrete floor slabs in detached garages, carports or porte-cocheres shall not have excessive pits, depressions, deterioration or unevenness equal to or exceeding 3/8 of an inch in any 32 inches. Separations or cracks in these slabs shall not equal or exceed 3/16 of an inch in width, except at expansion joints, or 1/8 of an inch in vertical displacement.
 - (6) A crack in exterior concrete shall not cause vertical displacement equal to or in excess of ¼ inch of an inch or horizontal separation equal to or excess of ¼ of an inch. The homeowner shall not over-water surrounding soil or allow the surrounding soil to become excessively dry. The homeowner shall not allow heavy equipment to be placed on the concrete.
 - (7) A separation in an expansion joint in an exterior concrete shall not equal or exceed 1/2 of an inch vertically from an adjoining section or one inch horizontally, including joint material.
 - (8) A separation in a control joint shall not equal or exceed 1/4 of an inch vertically or 1/2 of an inch horizontally from an adjoining section.
 - (9) Concrete stair steepness and dimensions, such as tread width, riser height, landing size and stairway width shall comply with the Code such that they perform their intended function without posing a safety risk.
 - (10) Concrete stairs or stoops shall not settle or heave in an amount such that they cannot perform their intended function without posing a safety risk. Concrete stairs or stoops shall not separate from the home in an amount equal to or exceeding one inch, including joint material.
 - (11) Handrails shall remain securely attached to concrete stairs.
 - (12) Plaster over concrete shall not flake off more than one square foot in one spot within 36 square inches or more than 3 feet over the entire surface of the home.
- § 6. Performance Standards for Framing
 - (a) Building and Performance Standard for Walls.
 - (1) Walls shall not bow or have depressions that equal or exceed 1/4 of an inch out of line within any 32-inch horizontal measurement as measured from the center of the bow or depression or 1/2 of an inch within any eight-foot vertical measurement.

Page 14 of 33

TAB A-14 ©

- (2) Walls shall be level, plumb and square to all adjoining openings or other walls within 3/8 of an inch in any 32inch measurement.
- (3) A crack in a beam or a post shall not equal or exceed 1/2 of an inch in width at any point along the length of the crack.
- (4) A non-structural post or beam shall not have a warp or twist equal or exceeding one inch in eight-feet of length. Warping or twisting shall not damage beam pocket.
- (5) Exterior sheathing shall not delaminate or swell. The homeowner shall not make penetrations in the exterior finish of a wall that allow moisture to come in contact with the exterior sheathing.
- (6) An exterior moisture barrier shall not allow an accumulation of moisture inside the barrier. The homeowner shall not make penetrations through the exterior moisture barrier that permit the introduction of moisture inside the barrier.
- (b) Performance Standards for Ceilings. A ceiling shall not bow or have depressions that equal or exceed 1/2 of an inch out of line within a 32-inch measurement as measured from the center of the bow or depression running parallel with a ceiling joist.
- (c) Performance Standards for Sub-floors.
 - (1) Under normal residential use, the floor shall not make excessive squeaking or popping sounds.
 - (2) Sub-floors shall not delaminate or swell to the extent that it causes observable physical damage to the floor covering or visually affects the appearance of the floor covering. Exposed structural flooring, where the structural flooring is used as the finished flooring, is excluded from the standard stated in this paragraph.
 - (3) Sub-flooring shall not have excessive humps, ridges or depressions within any room that equals or exceeds 3/8 of an inch in any 32-inch direction.
- (d) Performance Standards for Stairs.
 - (1) Stair steepness and dimensions such as tread width, riser height, landing size and stairway width shall be constructed in general compliance with the Code such that they perform their intended function without posing a safety risk.
 - (2) Under normal residential use, stairs shall not make excessive squeaking or popping sounds.

§ 7. Performance Standards for Drywall

- (a) A drywall surface shall not have a bow or depression that equals or exceeds 1/4 of an inch out of line within any 32inch horizontal measurement as measured from the center of the bow or depression or 1/2 of an inch within any eightfoot vertical measurement; such measurement to be made utilizing a straight-edge which is held reasonably parallel to the plane of the wall or ceiling surface.
- (b) A ceiling made of drywall shall not have bows or depressions that equal or exceed 1/2 of an inch out of line within a 32-inch measurement as measured from the center of the bow or depression running parallel with a ceiling joist or within 1/2 of an inch deviation from the plane of the ceiling within any eight-foot measurement; such measurement to be made utilizing a straight-edge which is held reasonably parallel to the plane of the wall or ceiling surface.
- (c) A drywall surface shall not have a crack such that any crack equals or exceeds 1/32 of an inch in width at any point along the length of the crack.

- (d) Crowning at a drywall joint shall not equal or exceed 1/4 of an inch within a twelve-inch measurement centered over the drywall joint. Crowning occurs when a drywall joint is higher than the plane of the drywall board on each side.
- (e) A drywall surface shall not have surface imperfections such as blisters, cracked corner beads, seam lines, excess joint compound or trowel marks that are visible from a distance of six feet or more in normal light. Minor variations in the 'splatter' or 'drag' appearance of texture which are the result of the original installation or subsequent repair work, visible from any distance, are not considered to be warrantable defects under this warranty.
- (f) A drywall surface shall not be out of level (horizontal), plumb (vertical) or square (perpendicular at a 90-degree angle) such that there are variations in those measurements to wall or surface edges at any opening, corner, sill, shelf, etc. shall not equal or exceed 3/8 of an inch in any 32-inch measurement along the wall or surface. This standard shall not apply to remodeling projects where existing conditions do not permit the Builder to achieve the performance standard. At or about the time of discovery of such a preexisting condition, a remodeler shall notify the homeowner, in writing, of any existing condition that prevents achievement of the standard. Accumulations of drywall compound in wall corners, at wallboard joints or outside corners, and at door, window or built-in cabinet openings, may not be the sole determinant that a wall or ceiling section is out of plumb or square.
- (g) Nails or screws shall not be visible in a drywall surface from a distance of 6 feet under normal lighting conditions.
- § 8. Performance Standards for Insulation
 - (a) Insulation shall be installed in the walls, ceilings and floors of a home in accordance with the building plan and specifications and the Code.
 - (b) Blown insulation in the attic shall not displace or settle so that it reduces the R-value below manufacturer's specifications, the building plans and the Code.
 - (c) A gap equal to or in excess of 1/4 of an inch between insulation batts or a gap between insulation batts and framing members is not permitted.
 - (d) In vented attics, insulation shall not cover or block a soffit vent to the extent that it blocks the free flow of air.
 - (e) In unvented attics, insulation shall be installed in compliance with the Code.
- § 9. Performance Standards for Exterior Siding and Trim
 - (a) Performance Standards for Exterior Siding.
 - (1) Exterior siding shall be equally spaced and properly aligned. Horizontal siding shall not equal or exceed 1/2 of an inch off parallel with the bottom course or 1/4 of an inch off parallel with the adjacent course from corner to corner.
 - (2) Siding shall not gap or bow. A siding end joint shall not have a gap that leaks or that equals or exceeds 1/4 of an inch in width. Siding end joint gaps shall be caulked. A bow in siding shall not equal or exceed 3/8 of an inch out of line in a 32-inch measurement.
 - (3) Nails shall not protrude from the finished surface of siding but nail heads may be visible on some products where allowed by the manufacturer's specifications.
 - (4) Siding shall not have a nail stain.
 - (5) Siding and siding knots shall not become loose or fall off.
 - (6) Siding shall not delaminate.
 - (7) Siding shall not cup in an amount equal to or exceeding 1/4 of an inch in a six-foot run.

Page 16 of 33

TAB A-14 ©

- (8) Siding shall not have cracks or splits that equal or exceed 1/8 of an inch in width.
- (b) Performance Standards for Exterior Trim.
 - (1) A joint between two trim pieces or between a trim piece and the adjoining material shall not have a separation that is equal to or exceeding 1/4 of an inch in width. All trim joints shall be caulked and shall not leak.
 - (2) Exterior trim and eave block shall not warp in an amount equal to or exceeding 1/2 of an inch in an eight-foot run.
 - (3) Exterior trim and eave block shall not cup in an amount equal to or in excess of a 1/4 of an inch in a six-foot run.
 - (4) Exterior trim and eave block shall not have cracks or splits equal to or in excess of 1/8 of an inch in average width.
 - (5) Trim shall not have nails that completely protrude through the finished surface of the trim but nail heads may be visible on some products. Some products specify that the nails be flush with the trim surface. When these products are used, visible nail heads are not considered protruding nails as long as they are painted over.
 - (6) Trim shall not have a nail stain.
- § 10. Performance Standards for Masonry including Brick, Block and Stone
 - (a) A masonry wall shall not bow in an amount equal to or in excess of one inch when measured from the base to the top of the wall. The standard set forth in this subsection does not apply to natural stone products.
 - (b) A masonry unit or mortar shall not be broken or loose.
 - (c) A masonry mortar crack shall not equal or exceed 1/8 of an inch in width.
 - (d) A masonry unit or mortar shall not deteriorate.
 - (e) Masonry shall not have dirt, stain or debris on the surface due to construction activities.
 - (f) A gap between masonry and adjacent material shall not equal or exceed 1/4 of an inch in average width and all such gaps shall be caulked.
 - (g) Mortar shall not obstruct a functional opening, such as a vent, weep hole or plumbing cleanout. The homeowner shall not put any material into weep holes. Weep holes are an integral part of the wall drainage system and must remain unobstructed.
- § 11. Performance Standards for Stucco
 - (a) Stucco surfaces shall not be excessively bowed, uneven, or wavy. This standard shall not apply to decorative finishes.
 - (b) Stucco shall not be broken or loose.
 - (c) Stucco shall not have cracks that equal or exceed 1/8 of an inch in width at any point along the length of the crack. The Builder shall not be responsible for repairing cracks in stucco caused by the homeowner's actions, including but not limited to periodic maintenance, caulking, painting, diversion of water onto the surface of the stucco, attachment of devices to the stucco surface, such as, but not limited to, patio covers, plant holders, awnings and hose racks.
 - (d) The homeowner shall not allow water from irrigation systems to contact stucco finishes.
 - (e) Stucco shall not have dirt, stain or debris on surface due to construction activities.

- (f) Stucco surfaces shall not have imperfections that are visible from a distance of six feet under normal lighting conditions that disrupt the overall uniformity of the finished pattern.
- (g) The lath shall not be exposed.
- (h) A separation between the stucco joints shall not equal or exceed 1/16 of an inch in width.
- (i) A separation between a stucco surface and adjacent material shall not equal or exceed 1/4 of an inch in width and all separations shall be caulked.
- (j) Stucco shall not obstruct a functional opening, such as a vent, weep hole or plumbing cleanout.
- (k) Stucco screed shall have a minimum clearance of at least 4 inches above the soil or landscape surface and at least 2 inches above any paved surface.
- (I) Exterior Insulation Finish Systems (EIFS) stucco screed shall clear any paved or unpaved surface by 6 inches.
- § 12. Performance Standards for Roofs
 - (a) Flashing shall prevent water penetration. The Builder shall not be responsible for leaks caused by extreme weather.
 - (b) The roof shall not leak.
 - (1) The Builder shall not be responsible for leaks caused by extreme weather, persistent or unusual weather.
 - (2) The homeowner shall perform periodic maintenance to prevent leaks due to build-up of debris, snow or ice. The homeowner shall take such action as is necessary to prevent downspouts and gutters from becoming clogged.
 - (c) A vent, louver or other installed attic opening shall not leak. The Builder shall not be responsible for leaks caused by extreme weather.
 - (d) A gutter or downspout shall not leak or retain standing water. After cessation of rainfall, standing water in an unobstructed gutter shall not equal or exceed 1/2 of an inch in depth.
 - (1) The Builder shall not be responsible for leaks caused by extreme weather, persistent or unusual weather.
 - (2) The homeowner shall maintain and clean gutters and downspouts to prevent buildup of debris or other obstructions.
 - (e) Shingles, tiles, metal or other roofing materials shall not become loose or fall off in wind speeds less than those set forth in the manufacturer's specifications.
 - (f) A skylight shall not leak.
 - (g) Water shall drain from a built-up roof within two hours after cessation of rainfall. The standard does not require that the roof dry completely within the time period.
 - (h) A roof tile shall not be cracked or broken. No shingle shall be broken so that it detracts from the overall appearance of the home.
 - (i) A pipe, vent, fireplace or other object designed to penetrate the roof shall not be located within the area of roof valley centerline without proper "cricketing" or other Code-approved water diversion methods.
 - (j) The exterior moisture barrier of the roof shall not allow moisture penetration. The homeowner shall not make penetrations through exterior moisture barrier of the roof.
- § 13. Performance Standards for Doors and Windows

- (a) Performance Standards for Both Doors and Windows.
 - (1) When closed, a door or window shall not allow excessive infiltration of air or dust.
 - (2) When closed, a door or window shall not allow excessive accumulation of moisture inside the door or window.
 - (A) The homeowner shall keep weep holes on windows and doors free of dirt buildup and debris, thereby allowing water to drain properly.
 - (B) Most door and window assemblies are designed to open, close and weep moisture--allow condensation or minor penetration by the elements to drain outside.
 - (3) Glass in doors and windows shall not be broken due to improper installation or construction activities.
 - (4) A screen in a door or window shall fit properly and shall not be torn or damaged due to construction activities. A screen shall not have a gap equal to or exceeding 1/4 of an inch between the screen frame and the window frame.
 - (5) There shall be no condensation between window and door panes in a sealed insulated glass unit. The homeowner shall not apply a tinted window film or coating to window or door panes in sealed insulated glass units.
 - (6) A door or window latch or lock shall close securely and shall not be loose or rattle.
 - (7) A door or window shall operate easily and smoothly and shall not require excessive pressure when opening or closing.
 - (8) A door or window shall be painted or stained according to the manufacturers' specifications.
- (b) Performance Standards for Windows. A double hung window shall not move more than two inches when put in an open position.
- (c) Performance Standards for Doors.
 - (1) A sliding door and door screen shall stay on track. The homeowner shall clean and lubricate sliding door or door screen hardware as necessary.
 - (2) The spacing between an interior door bottom and original floor covering, except closet doors, shall not exceed 1.5 inches and shall be at least 1/2 of an inch. The spacing between an interior closet door bottom and original floor covering shall not exceed two inches and shall be at least 1/2 of an inch.
 - (3) A door shall not delaminate.
 - (4) A door panel shall not split so that light from the other side is visible.
 - (5) A door shall open and close without binding.
 - (6) A door shall not warp to the extent that it becomes inoperable. A warp in a door panel shall not equal or exceed 1/4 of an inch from original dimension measured vertically, horizontally or diagonally from corner to corner.
 - (7) A storm door shall open and close properly and shall fit properly.
 - (8) When a door is placed in an open position, it shall remain in the position it was placed, unless the movement is caused by airflow.
 - (9) A metal door shall not be dented or scratched due to construction activities.
- (d) Performance Standards for Garage Doors.

Page 19 of 33

TAB A-14 ©

- (1) A metal garage door shall not be dented or scratched due to construction activities.
- (2) A garage door opener, if provided, shall operate properly in accordance with manufacturer's specifications. A homeowner shall maintain tracks, rollers and chains and shall not block or bump sensors to electric garage door openers.
- (3) A garage door shall not allow excessive water to enter the garage and the gap around the garage door shall not equal or exceed 1/2 of an inch in width.
- (4) A garage door spring shall operate properly and shall not lose appreciable tension, break or be undersized.
- (5) A garage door shall remain in place at any open position, operate smoothly and not be off track.
- § 14. Performance Standards for Interior Flooring
 - (a) Performance Standards for Carpet, Vinyl Flooring and Wood Flooring. Performance standards for ceramic tile, flagstone, marble, granite, slate, quarry tile, other hard surface floors, and finished concrete floors, are located in this section.
 - (b) Performance Standards for Carpet.
 - (1) Carpet shall not wrinkle and shall remain tight, lay flat and be securely fastened.
 - (2) Carpet seams may be visible but shall be smooth without a gap or overlap.
 - (3) Carpet shall not be stained or spotted due to construction activities.
 - (c) Performance Standards for Finished Concrete Floor.
 - (1) A finished slab, located in a living space that is not otherwise designed for drainage, shall not have pits, humps, depressions or unevenness that equals or exceeds 3/8 of an inch in any 32 inches. Finished concrete slabs in living spaces that are designed for drainage, such as a laundry room, are excepted from the standards stated in paragraph (1) of this subsection.
 - (2) Finished concrete slabs in living spaces shall not have separations, including joints, and cracks that equal or exceed 1/8 of an inch in width or 1/16 of an inch in vertical displacement.
 - (d) Performance Standards for Wood Flooring.
 - (1) Wood flooring shall not have excessive humps, depressions or unevenness that equals or exceeds 3/8 of an inch in any 32-inch direction within any room.
 - (2) Wood flooring shall remain securely attached to the foundation or sub-floor unless the wood flooring is designed to be installed without nails, glue, adhesives or fasteners.
 - (3) Wood flooring shall not have open joints and separations that equal or exceed 1/8 of an inch. These standards do not apply to non-hardwood species that contain greater moisture and may shrink after installation or structural floors that are designed to serve as the finished floor. If the floor is designed as a structural finish floor, the Builder must provide a written explanation of the characteristics of that floor to the homeowner prior to the execution of the contract or installation of the product, whichever occurs later.
 - (4) Strips of floorboards shall not cup in an amount that equals or exceeds 1/16 of an inch in height in a three-inch distance when measured perpendicular to the length of the board. This standard does not apply to non-hardwood species that typically shrink after installation or structural floors that are designed to serve as the finished floor. If the floor is designed as a structural finish floor, the Builder must provide a written explanation of the characteristics of that floor to the homeowner.

Page 20 of 33

- (5) Unless installed as a specialty feature, wood flooring shall not have excessive shade changes or discoloration due to the construction activities of the Builder.
- (6) Unless installed as a specialty feature, wood flooring shall not be stained, spotted or scratched due to construction activities of the Builder.
- (e) Performance Standards for Vinyl Flooring.
 - (1) Vinyl flooring shall be installed square to the most visible wall and shall not vary by 1/4 of an inch in any six-foot run.
 - (2) The seam alignment in vinyl flooring shall not vary such that the pattern is out of alignment in an amount that equals or exceeds 1/8 of an inch.
 - (3) Vinyl flooring shall remain securely attached to the foundation or sub-floor.
 - (4) A vinyl floor shall not have a depression that equals or exceeds 1/2 of an inch in any six-foot run. If a vinyl floor has a depression that exceeds the standard stated in this paragraph and the depression is due to construction activities, the Builder shall take such action as is necessary to bring the variance within the standard.
 - (5) A vinyl floor shall not have a ridge that equals or exceeds 1/2 of an inch when measured as provided in this paragraph. The ridge measurement shall be made by measuring the gap created when a six-foot straight edge is placed tightly three inches on each side of the defect and the gap is measured between the floor and the straight edge at the other end. If a vinyl floor has a ridge that fails to comply with the standard stated in this paragraph and the ridge is due to construction activities, the Builder shall take such action as is necessary to bring the variance within the standard.
 - (6) Vinyl floor shall not be discolored, stained or spotted due to the construction activities of the Builder.
 - (7) Vinyl flooring shall not be scratched, gouged, cut or torn due to construction activities.
 - (8) Debris, sub-floor seams, nails and/or screws shall not be detectable under the vinyl floor from a distance of three feet or more in normal light.
 - (9) Sub-flooring shall not cause vinyl flooring to rupture.
 - (10) A seam in vinyl flooring shall not have a separation that equals or exceeds 1/16 of an inch in width. Where dissimilar materials abut, there shall not be a gap equal to or greater than 1/8 of an inch.
- § 15. Performance Standards for Hard Surfaces, including Ceramic Tile, Flagstone, Marble, Granite, Slate, Quarry Tile, Finished Concrete or Other Hard Surfaces
 - (a) Performance Standards for Hard Surfaces Generally.
 - (1) A hard surface shall not break or crack due to construction activities.
 - (2) A hard surface shall remain secured to the substrate.
 - (3) A surface imperfection in floor hard surface shall not be visible from a distance of three feet or more in normal light. A surface imperfection in non-floor hard surface shall not be visible from a distance of two feet or more in normal light. If a hard surface fails to meet the standards stated in this paragraph due to construction activities, the Builder shall take such action as is necessary to bring the variance within the standard.
 - (4) Color variations between field hard surfaces and trim hard surfaces should not vary excessively due to construction activities. Natural products such as flagstone, marble, granite, slate and other quarry tile will have color variation.

- (5) Hard surface areas shall not leak.
- (6) The surfaces of two adjacent hard surfaces shall not vary in an amount equal to or exceeding 1/16 of an inch displacement at a joint (lippage) in addition to the actual manufacturing variations of the hard surface, such as warpage or dimensional differences in the hard surfaces, including thickness. If a joint between two hard surfaces fails to meet the performance standard stated in this paragraph (excluding trim pieces), the Builder shall take such action as is necessary to bring the variance within the standard.
- (7) Hard surface layout or grout line shall not be excessively irregular. Natural products such as flagstone, marble, granite, slate, and other quarry tile will have size variations that may create irregular layouts or grout lines.
- (8) Hard surface countertops shall be level to within 1/4 of an inch in any six-foot measurement.
- (9) Hard surface floors located in a living space that is not otherwise designed for drainage, shall not have pits, depressions, or unevenness that equals or exceeds 3/8 of an inch in any 32 inches. Finished hard surface floors located in living spaces that are designed for drainage, such as a laundry room, are excepted from the standards stated in paragraph (1) of this subsection.
- (b) Performance Standards for Grout.
 - (1) Grout shall not deteriorate.
 - (2) Cracks in grout shall not exceed 1/16 of an inch in width.
 - (3) Grout shall not change shade or discolor excessively due to construction activities.
- (c) Performance Standards for Concrete Countertops.
 - (1) A concrete countertop shall not have excessive pits, humps, depressions, or unevenness that equal or exceed 1/8 of an inch in any 32-inch measurement.
 - (2) A concrete countertop shall not have separations or cracks equal to or exceeding 1/16 of an inch in width or 1/64 of an inch in vertical displacement.
 - (3) A finished concrete countertop shall not be stained, spotted or scratched due to construction activities.
 - (4) A concrete countertop shall not have a chipped edge that extends beyond 1/16 of an inch from the edge of the countertop due to construction activities.
 - (5) A concrete countertop shall not change shade or discolor excessively due to construction activities.
- § 16. Performance Standards for Countertops and Backsplashes
 - (a) Performance Standards for Countertops and Backsplashes Generally.
 - (1) A countertop or backsplash shall be secured to substrate in accordance with manufacturer's specifications.
 - (2) For non-laminate countertops and backsplashes, the joints between countertop surfaces, between the countertop surface and the backsplash or side-splash and between adjoining backsplash panels may be visible but shall not separate.
 - (3) Countertops shall be level to within 1/4 of an inch in any six-foot measurement.
 - (4) A countertop surface or edge shall not be damaged, broken, chipped or cracked due to construction activities.
 - (5) A countertop shall not bow or warp in an amount equal to or exceeding 1/16 of an inch per lineal foot.
 - (6) Counter and vanity top material should not delaminate.

- (b) Performance Standards for Laminate Countertops and Backsplashes.
 - (1) Laminate countertops and backsplashes shall not delaminate and shall remain securely attached to the substrate. Delamination is the separation of the finish surface veneer from the substrate material.
 - (2) A seam in a laminate countertop or backsplash may be visible but shall not be separated or displaced.
 - (3) A surface imperfection in a laminate countertop or a backsplash shall not be visible from a distance of three feet or more when viewed in normal light due to construction activities.
- § 17. Performance Standards for Painting, Stain and Wall Coverings
 - (a) Performance Standards for Caulking. Interior caulking shall not deteriorate or crack excessively.
 - (b) Performance Standards for Painting and Stain.
 - (1) Paint or stain shall not have excessive color, shade or sheen variation. This standard shall not apply to stained woodwork.
 - (2) Paint shall cover all intended surfaces so that unpainted areas shall not show through paint when viewed from a distance of six feet in normal light.
 - (3) Interior paint or stain shall not deteriorate.
 - (4) Exterior paint or stain shall not deteriorate excessively.
 - (5) Paint over-spray shall not exist on any surface for which it was not intended.
 - (6) Interior varnish, polyurethane or lacquer finish shall not deteriorate.
 - (7) Exterior varnish, polyurethane or lacquer finishes shall not deteriorate excessively. Exterior varnish, polyurethane or lacquer finishes that are subject to direct sunlight are excluded from this standard.
 - (8) Interior painted, varnished or finished surface shall not be scratched, dented, nicked or gouged due to construction activities.
 - (9) A paint product shall perform as represented by the manufacturer to meet manufacturer's specifications for washability and/or scrubability.
 - (c) Performance Standards for Wall Coverings.
 - (1) A wall covering shall be properly secured to the wall surface and shall not peel or bubble.
 - (2) Pattern repeats in wall coverings shall match. Wall coverings shall be installed square to the most visible wall. Pattern repeats shall not vary in an amount equal to or exceeding 1/4 of an inch in any six-foot run.
 - (3) A wall covering seam shall not separate or gap.
 - (4) Lumps or ridges in a wall covering shall not be detectable from a distance of six feet or more in normal light.
 - (5) Wall coverings shall not be discolored, stained or spotted due to construction activities.
 - (6) Wall coverings shall not be scratched, gouged, cut or torn due to construction activities.
 - (7) Wall coverings shall perform as represented by the manufacturer to meet manufacturer's specifications for washability and/or scrubability.

§ 18. Performance Standards for Interior Trim

- (a) Performance Standards for Trim.
 - (1) An interior trim joint separation shall not equal or exceed 1/8 of an inch in width or shall not separate from adjacent surfaces equal to or in excess of 1/8 inch and all joints shall be caulked or puttied.
 - (2) The interior trim shall not have surface damage, such as scratches, chips, dents, gouges, splits, cracks, warping or cupping that is visible from a distance of six feet or more in normal light due to construction activities.
 - (3) A hammer mark on trim shall not be visible from a distance of six feet or more when viewed in normal light.
 - (4) A nail or nail hole in interior trim shall not be visible from a distance of six feet or more when viewed in normal light.
- (b) Performance Standards for Shelving. Shelving, rods and end supports shall be installed in accordance with the measurements stated in this subsection. The length of a closet rod shall not be shorter than the actual distance between the end supports in an amount equal to or exceeding 1/4 of an inch. The length of a shelf shall not be shorter than the actual distance between the supporting walls by an amount equal to or exceeding 1/4 of an inch. End supports shall be securely mounted.
- (c) Performance Standard for Cabinet Doors. Cabinet doors shall open and close with reasonable ease. Cabinet doors shall be even and shall not warp more than 1/4 inch when measured from the face to the point of the furthermost point of the door or drawer front when closed. Some warping, cupping, bowing or twisting is normally caused by surface temperature and humidity changes.
- § 19. Performance Standards for Mirrors, Interior Glass and Shower Doors
 - (a) A mirror, interior glass or shower door shall not be loose and shall be securely mounted or attached to the supporting surface. Fixtures, such as towel bars or door handles, shall be securely mounted.
 - (b) A mirror, interior glass or shower door shall not be damaged due to construction activities.
 - (c) A shower door shall not leak due to Builder fault or construction activities.
 - (d) Imperfections in a mirror or shower door shall not be visible from a distance of two feet or more when viewed in normal light.
 - (e) When opening and closing, a shower door shall operate easily and smoothly without requiring excessive pressure.
- § 20. Performance Standards for Hardware and Ironwork
 - (a) Performance Standards for Hardware.
 - (1) Hardware finishes shall not be tarnished, blemished, corroded or stained due to construction activities, unless the finish is installed as a specialty feature. The Builder is not responsible for tarnished, blemished, or stained hardware finishes that have been damaged by factors that are beyond the manufacturer's or the Builder's control such as the homeowner's use of abrasive pads or cleaners, harsh chemicals, alcohol, organic solvents or deterioration caused by exposure to outdoor elements such as salt air or humidity.
 - (2) Hardware shall function properly, without catching binding or requiring excessive force to operate.
 - (3) Hardware shall not be scratched, chipped, cracked or dented due to construction activities.

- (4) Hardware shall be installed securely and shall not be loose. The homeowner shall not exert excessive force on hardware.
- (b) Performance Standards for Interior Ironwork.
 - (1) Interior ironwork shall not rust.
 - (2) The Builder is not responsible for ironwork finishes that rust due to factors that are beyond the manufacturer's or the Builder's control such as the homeowner's use of abrasive pads or cleaners, harsh chemicals, alcohol, organic solvents or deterioration caused by exposure to humidity.
- § 21. Performance Standards for Fireplaces
 - (a) A refractory panel shall not crack or separate. The homeowner shall not use synthetic logs or other materials if not approved by the manufacturer.
 - (b) A fireplace door shall operate properly. Fireplace doors shall meet evenly and shall not be out of alignment from one another in an amount equal to or exceeding 1/8 of an inch in any direction.
 - (c) A fireplace shall not have a gas leak.
 - (d) Gas logs shall be positioned in accordance with the manufacturer's specifications. The homeowner shall not incorrectly reposition or relocate the logs after the original placement. The homeowner shall not place the logs in a manner that does not allow the flame to flow through the logs according to the manufacturer's specifications.
 - (e) A crack in masonry hearth or facing shall not be equal to or exceed 1/4 of an inch in width.
 - (f) A fireplace or chimney shall draw properly.
 - (g) A firebox shall not have excessive water infiltration under normal weather conditions.
 - (h) A fireplace fan shall not exceed the noise level established by the manufacturer's specifications.
- § 22. Performance Standards for Irrigation Systems
 - (a) An irrigation system shall not leak, break or clog due to construction activities or due to soil settlement.
 - (b) An irrigation system shall be installed such that sprinkler coverage shall be complete and water shall not spray an unintended area due to construction activities.
 - (c) The irrigation system control shall operate in accordance with manufacturer's specifications. The Builder shall provide the homeowner with instructions on the operation of the irrigation system at closing.
- § 23. Performance Standards for Fencing
 - (a) A fence shall not fall over and shall not lean in excess of two inches out of plumb due to construction activities.
 - (b) A wood fence board shall not be broken due to construction activities. Wood fence board shall not become detached from the fence due to construction activities of the Builder.
 - (c) A masonry unit or mortar in a fence shall not be broken or loose. A crack in a masonry unit shall not occur. A crack in the mortar shall not equal or exceed 1/8 of an inch in width.
 - (d) A masonry wall shall have adequate weep holes in the lowest course as required by the Code to allow seepage to pass through the wall.

§ 24. Performance Standards for Pest Control.

- (a) Eave returns, truss blocks, attic vents and roof vent openings shall not allow rodents, birds, and other similar pests into the home or attic space.
- § 25. Performance Standards for Plumbing
 - (a) Performance Standards for Plumbing Accessories.
 - (1) A fixture surface shall not have a chip, crack, dent or scratch due to construction activities.
 - (2) A fixture shall not have tarnish, blemishes or stains unless installed as a specialty feature. Fixture finishes that are tarnished, blemished or stained due to high iron, manganese or other mineral content in water are excluded from this standard.
 - (3) A fixture or fixture fastener shall not corrode. A Builder is not responsible for corrosion caused by factors beyond the manufacturer's or the Builder's control, including the homeowner's use of corrosive chemicals or cleaners or corrosion caused by water content.
 - (4) A decorative gas appliance shall be installed in accordance with manufacturer's specifications and when so installed shall function in accordance with manufacturer's representations.
 - (5) Fixtures shall be secure and not loose. The homeowner shall not exert excessive force on a fixture.
 - (6) A fixture stopper shall operate properly and shall retain water in accordance with the manufacturer's specifications.
 - (7) The toilet equipment shall not allow water to run continuously. If toilet equipment allows water to run continuously, the homeowner shall shut off the water supply or take such action as is necessary to avoid resulting damage.
 - (8) A toilet shall be installed and perform in accordance with the manufacturer's specifications. In the event of water spillage, the homeowner shall shut off the water supply and take such action as is necessary to avoid resulting damage.
 - (9) A tub or shower pan shall not crack.
 - (10) A tub or shower pan shall not squeak excessively.
 - (11) A water heater shall be installed and secured according to the manufacturer's specifications and the Code.
 - (12) A waste disposal unit shall be installed and operate according to the manufacturer's specifications.
 - (13) A faucet or fixture shall not drip or leak. This standard does not include drips or leaks due to debris or minerals from the water source, unless it is due to construction activities.
 - (14) A sump pump shall be installed in accordance with the manufacturer's specifications and shall operate properly when so installed.
 - (b) Performance Standards for Pipes and Vents.
 - (1) A sewer gas odor originating from the plumbing system shall not be detectable inside the home under conditions of normal residential use. The homeowner shall keep plumbing traps filled with water.
 - (2) A vent stack shall be free from blockage and shall allow odor to exit the home.

- (3) A water pipe shall not make excessive noise such as banging or hammering repeatedly. A water pipe subject to expansion or contraction of the pipe as warm or cool water flows through the pipe may cause a "ticking" sound temporarily. The standard stated in this subsection does not require a Builder to remove all noise attributable to water flow and pipe expansion.
- § 26. Performance Standards for Heating, Cooling and Ventilation
 - (a) Performance Standards for Heating and Cooling.
 - (1) A condensation line shall not be obstructed due to construction activities. The homeowner shall periodically check for the free flow of condensate (water) from the line and clear the line when necessary.
 - (2) A drip pan and drain line shall be installed under a horizontal air handler as per the Code. The homeowner shall periodically check for the free flow of condensate (water) from the line and clear the line when necessary.
 - (3) Insulation shall completely encase the refrigerant line according to Code. The homeowner shall ensure that insulation on the refrigerant line is not damaged or cut due to home maintenance or landscape work.
 - (4) An exterior compressor unit shall be installed in accordance with the manufacturer's instructions and specifications. The bottom of the exterior compressor unit support shall not be below ground level. The homeowner shall ensure that settlement of the exterior compressor unit pad does not occur due to home maintenance, landscape work or excessive water from irrigation.
 - (b) Performance Standards for Venting.
 - (1) An appliance shall be vented according to the manufacturer's specifications.
 - (2) Back draft dampers shall be installed and function according to the manufacturer's specifications.
 - (c) Performance Standards for Ductwork. Ductwork shall not make excessive noise.
 - (1) The flow of air, including its velocity, or the expansion of ductwork from heating and cooling may cause common "ticking" or "crackling" sounds. The Builder shall have no responsibility for correction in such cases.
 - (2) The homeowner shall not place any object on the ductwork.
- § 27. Performance Standards for Electrical Systems and Fixtures
 - (a) Excessive air infiltration shall not occur around electrical system components or fixtures.
 - (b) A fixture or trim plate shall not be chipped, cracked, dented or scratched due to construction activities.
 - (c) A fixture or trim plate finish shall not be tarnished, blemished or stained due to construction activities.
 - (d) A fixture, electrical box or trim plate shall be installed in accordance with the Code and shall be plumb and level.
 - (e) Fixtures, such as lights, fans and appliances shall operate properly when installed in accordance with the manufacturer's specifications.
 - (f) A smoke detector shall operate according to the manufacturer's specifications and shall be installed in accordance with the Code.
 - (g) An exhaust fan shall operate within the manufacturer's specified noise level.
 - (h) A carbon monoxide detector shall operate according to the manufacturer's specifications and shall be installed in accordance with the Code.

TWO YEAR WARRANTY PERIOD

§ 28. Performance Standards for Plumbing Delivery Systems

- (a) Performance Standards for Pipes including Water and Gas Pipes, Sewer and Drain Lines, Fittings and Valves but not including pipes included in a Landscape Irrigation System.
 - (1) Pipes shall be installed and insulated in accordance with the Code and manufacturer's specifications.
 - (A) If a water pipe bursts, the Builder shall take such action as is necessary to bring the variance within the standard stated in paragraph (1) of this subsection.
 - (B) The homeowner is responsible for insulating and protecting exterior pipes and hose bibs from freezing weather and for maintaining a reasonable temperature in the home during periods of extremely cold weather. The homeowner is responsible for maintaining a reasonable internal temperature in a home regardless of whether the home is occupied or unoccupied and for periodically checking to ensure that a reasonable internal temperature is maintained.
 - (2) A water pipe shall not leak. The homeowner shall shut off water supply immediately if such is required to prevent further damage to the home.
 - (3) A gas pipe shall not leak, including natural gas, propane or butane gas. If a gas pipe is leaking, the homeowner shall shut off the source of the gas if the homeowner can do so safely.
 - (4) Water pressure shall not exceed 80 pounds per square inch in any part of the water supply system located inside the home. Minimum static pressure at the building entrance for either public or private water service shall be 40 pounds per square inch in any part of the water supply system. This standard assumes the public or community water supply reaches the home side of the meter at 40 pounds per square inch. The Builder is not responsible for water pressure variations originating from the water supply source.
 - (5) A sewer, drain, or waste pipe shall not become clogged or stopped up due to construction activities.
 - (A) The Builder shall take such action as is necessary to unclog a sewer, drain or waste pipe that is clogged or stopped up due to construction activities.
 - (B) The homeowner shall shut off water supply immediately if such is required to prevent damage to the home.
- (b) Performance Standards for Individual Wastewater Treatment Systems. A wastewater treatment system should be capable of properly handling normal flow of household effluent in accordance with the Texas Commission on Environmental Quality requirements.
 - (1) The Builder shall take such action as is necessary for the wastewater treatment system to perform within the standard stated in this subsection.
 - (2) The Builder is not responsible for:
 - (A) system malfunctions or damage due to the addition of a fixture, equipment, appliance or other source of waste or water into the septic system by a person other than the Builder or a person working at the Builder's direction; or
 - (B) malfunctions or limitations in the operation of the system attributed to a design restriction imposed by state, county or local governing agencies; or

(C) malfunctions caused by freezing, soil saturation, soil conditions, changes in ground water table or any other acts of nature.

§ 29. Performance Standards for Heating, Air Conditioning and Ventilation Delivery Systems

- (a) A refrigerant line shall not leak. Condensation on a refrigerant line is not a leak.
- (b) Performance Standards for Heating and Cooling Functions.
 - (1) A heating system shall produce an inside temperature of at least 68-degrees Fahrenheit as measured two feet from the outside wall of a room at a height of three feet above the floor under local outdoor winter design conditions as specified in the Code. Temperatures may vary up to 4-degrees Fahrenheit between rooms but no less than the standard set forth above in paragraph (1) of this subsection. If the homeowner modifies or changes the size or configuration of the system or the square footage associated property or dwelling, the heating system or the ductwork shall negate the Builder's responsibility to take measures to meet this performance standard.
 - (2) An air-conditioner system shall produce an inside temperature of at most 78-degrees Fahrenheit as measured in the center of a room at height of five feet above the floor, under local outdoor summer design conditions as specified in the Code. (In the case of outside temperatures exceeding 98 degrees Fahrenheit, the system shall keep the inside temperature 20 degrees cooler than the outside temperature.) This standard does not apply to evaporative or other alternative cooling systems or if the homeowner makes changes to the size or configuration of the home, the air-conditioning system or the ductwork. Internal temperatures may vary up to 4-degrees Fahrenheit between rooms but no more than the standard set forth above in paragraph (2) of this subsection. If the homeowner modifies or changes the size or configuration of the system or the square footage associated property or dwelling, the cooling system or the ductwork shall negate the Builder's responsibility to take measures to meet this performance standard.
 - (3) A thermostat reading shall not differ by more than 4-degrees Fahrenheit from the actual room temperature taken at a height of five feet above the floor in the center of the room where the thermostat is located. The stated performance standard is related to the accuracy of the thermostat and not to the performance standard of the room temperature.
 - (4) Heating and cooling equipment shall be installed and secured according to the manufacturer's instructions and specification and shall not move excessively.
- (c) Performance Standards for Vents, Grills or Registers.
 - (1) A vent, grill or register shall operate easily and smoothly when applying normal operating pressure. If a vent, grill or register does not operate easily and smoothly when applying normal pressure when adjusting, the Builder shall repair the vent, grill or register so that it operates with ease of use when applying normal operating pressure.
 - (2) A vent, grill or register shall be installed in accordance with the Code and manufacturer's instructions and specifications and shall be secured to the underlying surface.
- (d) Performance Standards for Ductwork.
 - (1) Ductwork shall be insulated in unconditioned areas according to Code.
 - (2) Ductwork shall be secured according to the manufacturer's instructions and specifications and it shall not move excessively.

(3) Ductwork shall be sealed and shall not separate or leak in excess of the standards set by the Code.

§ 30. Performance Standards for Electrical Delivery Systems

- (a) Performance Standards for Electrical Wiring.
 - (1) Electrical wiring installed inside the home shall be installed in accordance with the Code and any other applicable electrical standards and shall function properly from the point of demarcation, as determined by the respective utility. The Builder shall not be responsible for utility improvements from the meter/demarcation point to the utility poles or the transformer.
 - (2) Electrical wiring shall be capable of carrying the designated load as set forth in the Code. All electrical equipment shall be used for the purposes and/or capacities for which it was designed and in accordance with manufacturer's specifications.
- (b) Performance Standards for the Electrical Panel, Breakers and Fuses.
 - (1) The electrical panel and breakers shall have sufficient capacity to provide electrical service to the home during normal residential usage. The Builder is not responsible for electrical service interruptions caused by external conditions such as power surges, circuit overloads and electrical shorts.
 - (2) The electrical panel and breakers shall have sufficient capacity to provide electrical service to the home during normal residential usage such that a circuit breaker shall not trip and fuses shall not blow repeatedly under normal residential electric usage. The Builder is not responsible for circuit breaker trips or blown fuses that have functioned as designed to protect the home from external conditions such as power surges, circuit overloads and shorts.
- (c) Performance Standards for Electric Outlets with Ground Fault Interrupters.
 - (1) Electrical outlets with ground fault interrupters shall be installed and operate in accordance with the Code and manufacturer's specifications. If ground fault interrupters trip repeatedly under normal residential usage, the Builder shall take such action as is necessary to ensure that the electrical outlets with ground fault interrupters are installed in accordance with the Code and manufacturer's instructions and specifications and that they operate properly during normal residential electrical usage.
 - (2) The homeowner shall not plug appliances that require constant electrical flow, such as refrigerators and freezers, into an outlet with a ground fault interrupter.
- (d) Performance Standards for Fixtures, Outlets, Doorbells and Switches.
 - (1) An outlet, doorbell or switch shall be installed in accordance with the manufacturer's specifications and the Code and shall operate properly when installed in accordance with the manufacturer's specifications and the Code.
 - (2) A fixture, electrical box or trim plate shall be installed in accordance with the Code and manufacturer's specifications and shall be properly secured to the supporting surface.
 - (3) A light shall not dim, flicker or burn out repeatedly under normal circumstances. A lighting circuit shall meet the Code.
- (e) Performance Standards for Wiring or Outlets for Cable Television, Telephone, Ethernet or Other Services.
 - (1) Wiring or outlets for cable television, telephone, ethernet or other services shall be installed in accordance with the Code and any applicable manufacturer's specifications. A Builder is not responsible for the failure of wiring or other utility service connectors or conduits that begin before the point at which the service enters the home.

(2) Wiring or outlets for cable television, telephone, ethernet or other services inside the home or on the home side of the meter/demarcation point shall function properly when installed in accordance with the performance standard in paragraph (1) of this subsection. A Builder is not responsible for the failure of wiring or other utility service connectors or conduits that begin before the point at which the service enters the home.

TEN YEAR WARRANTY PERIOD

- § 31. Performance Standards for Major Structural Components
 - (a) Performance Standards for Slab-on-Ground Foundations.
 - (1) Slab-on-ground foundations should not move differentially after they are constructed, such that a tilt or deflection in the slab in excess of the standards defined below arises from actual post-construction movement. The protocol and standards for evaluating slab-on-ground foundations shall follow all of the provisions of the ASCE Guidelines with the following modifications:
 - (A) Overall deflection from original construction shall be no greater than the overall length over which the deflection occurs divided by 360 (L/360) and must not have more than one associated symptom of distress resulting from said overall deflection, as described in Section 5 of the ASCE Guidelines, and that results in actual observable physical damage to the home. L shall be defined as the edge-to-edge distance across any slab cross-section for which overall deflection is calculated, but the minimum L shall be not less than 25 feet. Calculations of overall deflection shall be based upon the change in elevation at each point for which an Original Construction Elevation was taken. If obstructions restrict access to original Original Construction Elevations are available, the slab may be assumed to have been built as much as +/- ³/₄ of an inch, provided that this assumption is based upon other evidence of unlevelness, such as the four items listed in Section 5.5 (Deflection) of the ASCE Guidlelines. A deflection analysis must be based upon a minimum of three co-planar relative elevation data points two end points that form a straight reference line along the evaluated section and a third point anywhere along the deformed surface that reflects a deviation of the foundation surface from the reference line.
 - (B) The slab shall not tilt after construction in excess of one percent across any edge-to-edge dimension of the home or cause structural component(s) or masonry veneer to rotate into a structurally unstable position such that the weight vector of the component part falls outside the middle third of its bearing area. Calculations of overall tilt shall be based upon the change in elevation at the respective edge points for which an Original Construction Elevation was taken. If obstructions restrict access to original Original Construction Elevation points, interpolation between current elevations points may be employed. If no Original Construction Elevations are available, the slab may be assumed to have been built as much as +/- ³/₄ of an inch, provided that this assumption is based upon other evidence of unlevelness, such as the four items listed in Section 5.5 (Deflection) of the ASCE Guidlelines.
 - (2) If measurements and associated symptoms of distress show that a slab-on-ground foundation does not meet the deflection or tilt standards stated in paragraph (1) of this subsection, the Builder shall implement the recommendations of a Texas licensed professional engineer, which shall be based on the appropriate remedial measures as described in Section 7 of the ASCE Guidelines. Localized measurements of deflection that are claimed to be outside of performance standards, Code or tolerances are not warranted and there is no Builder

Responsibility for correction or otherwise. By definition, tilt is a global mechanism of planar rotation across the entire foundation, edge-to-edge; therefore, local tilt does not exist and cannot be analyzed.

- (b) Performance Standards for Raised-Floor Foundations (i.e. Pier-and-Beam, Elevated Concrete Slabs on Forms, etc.).
 - (1) Raised-floor foundations should not move differentially after they are constructed, such that a tilt or deflection in the floor surface in excess of the standards defined below arises from actual post-construction movement. The protocol and standards for evaluating raised-floor foundations shall follow the ASCE Guidelines with the following modifications:
 - (A) A raised-floor foundation shall not deflect between supports more than L/360 from original construction and have that movement create actual observable physical damage to the components of the home identifiable in Section 5.3 of the ASCE Guidelines. L shall be defined as the edge-to-edge distance across any foundation cross-section for which overall deflection is calculated. Calculations of overall deflection shall be based upon the change in elevation at each point for which an Original Construction Elevation was taken. If obstructions restrict access to original Original Construction Elevation points, interpolation between current elevations points may be employed. If no Original Construction Elevations are available, the slab may be assumed to have been built as much as +/- ¾ of an inch, provided that this assumption is based upon other evidence of unlevelness, such as the four items listed in Section 5.5 (Deflection) of the ASCE Guidleline. A deflection analysis must be based upon a minimum of three co-planar relative elevation data points – two end points that form a straight reference line along the evaluated section and a third point anywhere along the deformed surface that reflects a deviation of the floor surface from the reference line. The distance from the deformed surface to the reference line shall be measured perpendicular to the reference line.
 - (B) A raised-floor foundation shall not tilt after construction in excess of one percent across any edge-to-edge dimension of the Improvements or cause structural component(s) or masonry veneer to rotate into a structurally unstable position such that the weight vector of the component part falls outside the middle third of its bearing area. Calculations of overall tilt shall be based upon the change in elevation at the respective perimeter points for which an Original Construction Elevation was taken. If obstructions restrict access to original Original Construction Elevation points, interpolation between current elevations points may be employed. If no Original Construction Elevations are available, the slab may be assumed to have been built as much as +/- ³/₄ of an inch, provided that this assumption is based upon other evidence of unlevelness, such as the four items listed in Section 5.5 (Deflection) of the ASCE Guidleline.
 - (C) If a raised-floor foundation deflects more than L/360 from its original construction elevation and the movement has created actual observable physical damage to the components of a home identifiable in Section 5.3 of the ASCE Guidelines, the Builder shall implement the recommendations of a Texas licensed Professional Engineer, which shall be based on applicable remedial measures as described in Section 7 of the ASCE Guidelines.
 - (2) If measurements and associated symptoms of distress show that a raised floor foundation does not meet the deflection or tilt standards stated in paragraph (1) of this subsection, the Builder shall implement the recommendations of a Texas licensed professional engineer, which shall be based on the appropriate remedial measures as described in Section 7 of the ASCE Guidelines. Localized measurements of defection that are claimed to be outside of performance standards, Code or tolerances are not warranted and there is no Builder Responsibility for correction or otherwise. Attempted measurements of localized slopes, not tilt, which are not warranted, and there is no Builder Responsibility for correction or otherwise.
- (c) Major Structural Components other than Slab-on-Ground Foundations and Raised Floor Foundations.

- (1) A defined structural component, other than the concrete elements of a slab-on-ground foundation or a raised floor foundation, shall not crack, bow, become distorted or deteriorate, such that it compromises the structural integrity of a home or the performance of a structural system of the home resulting in actual observable physical damage to a component of the home.
- (2) If a structural component of a home, other than the concrete elements of a slab-on-ground foundation or a raised floor foundation, cracks, bows, is distorted or deteriorates such that it results in actual observable physical damage to a component of the home, the Builder shall take such action as is necessary to repair, reinforce or replace such structural component to restore the structural integrity of the home or the performance of the affected structural system.
- (3) Deflected structural components.
 - (A) A structural component, other than the foundation, shall not deflect more than the ratios allowed by the Code.
 - (B) If a structural component of the home, other than the foundation, is deflected more than the ratios allowed by the Code, the Builder shall repair, reinforce or replace such structural component to restore the structural integrity of the home or the performance of the affected structural system.
- (4) Damaged structural components.
 - (A) A structural component, other than the foundation, shall not be so damaged that it compromises the structural integrity or performance of the affected structural system.
 - (B) If a structural component, other than the foundation, is so damaged that it compromises the structural integrity or performance of a structural system of the home, the Builder shall take such action as is necessary to repair, reinforce or replace such structural component to restore the structural integrity of the home or the performance of the affected structural system.
- (5) Separated structural components.
 - (A) A structural component, other than the foundation, shall not separate from a supporting member more than 3/4 of an inch or such that it compromises the structural integrity or performance of the system.
 - (B) If a structural component, other than the foundation, is separated from a supporting member more than 3/4 of an inch or separated such that it compromises the structural integrity or performance of a structural system of the home, the Builder shall take such action as necessary to repair, reinforce or replace such structural component to re-establish the connection between the structural component and the supporting member, to restore the structural integrity of the home and the performance of the affected structural system.

FORM F-2		OFFICER REPORT						
	Agenda Item Number	5.6	Item Title	VP-Technical				
TEXAS SECTION	Date	07/21/23	Reported by	Mark Boyd PhD, PE				
1 c	Purpose	Summer 2022-2023	23 Executive Committee Meeting					

OFFICER ACTIVITIES

- Attended all board and committee progress check meetings.
- Participated in all CECON 2023 Planning Committee and Programs Committee meetings
- Following through with CECON 2023 Planning and Programs Committee to get the CECON institute program lined up, now fully planned and confirmed.
- Monitoring formal partnership agreement performance with TxEWRI, TxGI, TxSEI and TxT&DI
- Monitoring MOU agreement with TxUESI
- Facilitating with institutes to comply with program and sponsorship contributions according to their respective agreements.

WEBINAR ACTIVITIES

- Ten (10) webinars have been presented so far in 2022-2023 Section year
- Webinars have touched a wide range of subjects. The first June 2023 webinar tested a new "talk show" style format about engineering communication. Future webinars will include an update of the Beyond Storms electric grid committee and a presentation by Dr. Kate Smits, recently appointed chair of the SMU Civil/Environmental Engineering program, about research on Green House Gas reduction opportunities.
- See attached table of webinars presented and future webinars planned for the remainder of 2022-2023 section year, including attendee and registration count for each webinar presented so far.

The goal is to present at least two webinars per month. VP Tech is actively working to enlist institute assistance to contribute webinar content for remaining available dates in August, Sept and October 2023.

INSTITUTE ACTIVITIES

- Conducted virtual Institute meetings on the second Tuesday of each month since the last VP Tech report. John Mudd and Andrew Domke are invited to attend the meetings to directly communicate CECON 2023 requirements and expectations to leaders of institute partners and MOU participants.
- During the monthly meetings, institute leaders at branch and state level report and discuss successes and lessons learned in their branch and section activity and get feedback and encouragement from the group.
- The monthly meetings have also been very useful in keeping institute partners TxEWRI, TxGI TxSEI and TxT&DI as well as MOU participant TxUESI engaged in promoting CECON 2023. VP Tech regularly encourages institutes to recruit attendees, exhibitors, and sponsors for the event.
- Institute attendance at the monthly meetings has been high with all active institutes represented, most of the time, but a drop-off in attendance was experienced during the most recent June meeting.

TECHNICAL INSTITUTE CHAPTERS & GROUPS		CHAIRS
TxCI Chapter		OPEN
TxEWRI Chapter		Curtis Beitel PE & Russell Erskine PE
TxGI Chapter		Robert Lawrence PE
TxSEI Chapter		Marcelo Dasilva PE
TxT&DI Chapter		Surya Bhandari PE
TXUESI Chapter		Bobby Nagel PE
Forensics Group		OPEN
ITEMS FOR AGENDA		open to brief/limited impromptu discussion, Q&A or mmittee leads about feedback concerning VP Tech

Date	Presenter Name	Presenter Email	Webinar Topic	Subject/Discipline	Confirmed	Details Received	Revenue	Registered	Attended	% Attendance	Avg Rev/Attendee
1/11/2022	Michael Bloom	mbloom@rgmiller.com	An Intro to the Envision Sustainable Infrastructure Framework	Sustainability	Yes	Yes	\$ 360	42	25	60%	\$ 14.40
2/8/2022	Dacia Coffey	dacia@themarketingblender.com	Corporate Caffeine: How to Fire Up Your Professional Success	Communication	Yes	Yes	\$ 750	132	58	44%	\$ 12.93
3/2/2022	Paula Paciorek		Strengthening Water Conservation for a Resilient Houston	water resources	Yes	Yes	\$ 320	26	23	88%	\$ 13.91
3/22/2022	Dacia Coffey	dacia@themarketingblender.com	Communication for Engineers Pt 2	Communication	Yes	Yes	\$ 750	60	24	40%	\$ 31.25
4/26/2022	Steve Hiner	Ishiner@comcast.net	Ethics	ethics	Yes	Yes	\$ 785	53	39	74%	\$ 20.13
5/10/2022	Dacia Coffey	dacia@themarketingblender.com	Communication for Engineers Pt 3	Communication	Yes	Yes	\$ 750	168	60	36%	\$ 12.50
5/26/2022	David Eastwood	david.eastwood@geotecheng.com	Pt 1: Slope Stability, Ditches, Embankments & Detention Ponds	geotech	Yes	Yes	\$ -	740	358	48%	\$-
6/9/2022	David Eastwood	david.eastwood@geotecheng.com	Pt 2: Design of Bridge Structures	geotech	Yes	Yes	\$ -	772	332	43%	\$-
6/23/2022	Patrick Tarlton	ptarlton@concretepipe.org	Engineering communication with elected officials	communication	Yes	Yes	\$ 225	21	19	90%	\$ 11.84
7/14/2022	David Eastwood	david.eastwood@geotecheng.com	Pt 3: Design & Construction of Roadways	geotech	Yes	Yes	\$ 750	838	235	28%	\$ 3.19
7/28/2022	David Eastwood	david.eastwood@geotecheng.com	Pt 4: Design & Construction of Water and Wastewater Facilities	geotech	Yes	Yes	\$ 750	756	232	31%	\$ 3.23
8/9/2022	Geoff Roberts	groberts@rrrrinvestments.com	Part 1: Summary & Recommendations	storms	Yes	Yes	\$ -	146	90	62%	\$-
8/23/2022	Geoff Roberts		Part 2: Energy & Electricity	energy	Yes	Yes	\$ -	144	84	58%	\$-
9/6/2022	Mark Boyd et al		Part 3: Water Resources	transportation	Yes	Yes	\$ -	154	65	42%	\$-
9/20/2022	Walt Catlett	wcatlett@catlettengineering.com	Trench Safety for Engineers OR Bridge Preservation Fundamentals	geotech?	Yes	Yes	\$ -	36	22	61%	\$-
10/25/2022	Geoff Roberts		Part 4: Telco & Transportation	water	Yes	Yes	\$ -	231	73	32%	\$-
11/29/2022	Dallas May	may@lcaenvironmental.com	US 67 Groundwater Contamination Project: Dallas District	transprtation & environmental	Yes		ş -	50	38	76%	\$-
12/13/2022	Geoff Roberts		Part 5: Wrap up, conclusions and recommendations.	storms	Yes	Yes	ş -	140	53	38%	\$ -
								4500	1920	E 29/	695%

Date	Time	Presenter Name	Presenter Email	Webinar Topic	Subject/Discipline	Confirmed	Details Received	Revenue	Registered	Attended	% Attendance	Avg Rev/Attendee
2/28/2023	12 - 1 PM CT	Oliver Smith	mmmoesmith@gmail.com	Texas Power Grid Readiness, An Update	winter, power	Yes	Yes	\$.	91	51	56%	\$ -
3/28/2023	12 - 1 PM CT	Luke Cooper	Luke Cooper < lcooper@ltraengineers.com>	Ground Penetrating Radar	UESI	Yes	Yes	\$ 670	67	57	85%	\$ 11.75
3/30/2023	12 - 1:30 PM CT	David Eastwood	david.eastwood@geotecheng.com	Geotechnical Considerations for the Design of Bridge Structures	geotechnical	Yes	Yes	\$ -	122	84	69%	\$ -
4/27/2023	1 - 3 PM CT	David Eastwood	david.eastwood@geotecheng.com	Geotechnical & Environmental Considerations for the Design & Construction of Roadways	geotechnical	Yes	Yes	\$.	208	133	64%	\$ -
5/23/2023	12 - 1 PM CT	David Rivera PhD, PE, CFM	david.rivera@freese.com	Statewide Flood Plan Update	ewri	Yes	Yes	\$ 760	76	59	78%	\$ 12.88
6/13/2023	12 - 1 PM CT	Jennifer Cottingham & Mark Boyd PhD, PE	jcottingham@lja.com	Technical Writing Skills for Engineering Professionals	writing	Yes	Yes	\$ ·			#DIV/01	#DIV/01
6/27/2023	12 - 1 PM CT	Fouad Jaber, Kate Zielke, TBD	fouad.jaber@ag.tamu.edu; KZielke@nctcog.org; TBD	Integrated Transportation and Stormwater Infrastructure Project	tdi/ewri			\$ ·			#DIV/01	#DIV/01
7/11/2023	12 - 1 PM CT	Geoff Roberts & Oliver Smith		Beyond Storms Updates	storms	Yes	title/desc	\$ -			#DIV/01	#DIV/0!
7/25/2023	12 - 1 PM CT	Vance Pool	vpool@euclidchemical.com	Concrete Cracks	structural	Yes	Yes	\$.			#DIV/01	#DIV/0!
7/27/2023	1 - 2:30 PM CT	David Eastwood	david.eastwood@geotecheng.com	Geotechnical Considerations for Slope Stability and Erosion Protection for Ditches, Embankments & Detention Ponds	geotechnical	Yes	Yes	\$.			#DIV/01	#DIV/0!
8/8/2023	12 - 1 PM CT	Kathleen Smits PhD, PE	ksmits@smu.edu	GHG Reduction Opportunities through Detection and Quantification of Belowground Natural Gas Pipeline Leaks	sue	Yes	Yes	\$.			#DIV/01	#DIV/0!
8/22/2023	12 - 1 PM CT							\$ ·			#DIV/01	#DIV/01
8/31/2023	1 - 3 PM CT	David Eastwood	david.eastwood@geotecheng.com	Geotechnical Considerations for the Design of Retaining Walls in TX	geotechnical	Yes	Yes	\$ -			#DIV/01	#DIV/0!
9/12/2023	12 - 1 PM CT							\$.			#DIV/01	#DIV/0!
9/26/2023	12 - 1 PM CT							\$.			#DIV/01	#DIV/0!
0/10/2023	12 - 1 PM CT							\$.			#DIV/01	#DIV/0!
0/24/2023	12 - 1 PM CT							\$.			#DIV/01	#DIV/0!
1/14/2023	12 - 1 PM CT							\$.			#DIV/01	#DIV/0!
1/28/2023	12 - 1 PM CT							\$ -			#DIV/01	#DIV/0!
2/12/2023	12 - 1 PM CT							\$.			#DIV/01	#DIV/0!
									564	384	#DIV/01	#DIV/0!

FORM F-2		OFFICER REPORT						
	Agenda Item Number	5.7	Item Title	Treasurer				
TEXAS SECTION	Date	07/21/23	Reported by	Glenn Goldstein PE				
	Purpose	Summer 2022-2023	3 Executive Com	mittee Meeting				

OFFICER ACTIVITIES

- Reviewed March 2023 through April 2023 financials and updated budget to align with the Texas Section's CPA (Ron Meyer PLLC) reconciled reports. Uploaded to SharePoint site for BOD access.
- Reviewed May 2023 financials and updated budget to align with draft expenditures prepared by the Texas Section's CPA.
- Kicked-off the FY24 operating budget update with ExCOM members. A goal of the budget will be to align with the 2022-2026 Strategic Plan. This is the estimated timeline for the budget update process: June/July: Treasurer and Assistant Treasurer meetings with ExCom members on budget updates 7/21: Treasurer's update on the budget process at Summer ExCom Meeting 8/4: Deadline to receive budget updates from ExCom members 8/16: Draft prelim budget is shared during Q4 Leadership Call By 9/5: All edits received and prelim budget is shared with BOD for review 9/22: Provide annual budget proposal to the BOD at CECON
- Reviewed Society's annual section dues collection program and changes for FY24.
- Texas Section's FY22 taxes were completed and submitted by the Texas Section's CPA in May and received by Society without comments.

FINANCIAL REPORTS

Monthly Financials for April 30, 2023 attached (includes CECON reports from Section's accounts):

		FY Balance	Budget Expended	<u>t</u>
4.7a Financia	I Summary			
General				
• Y	TD Revenue	\$479,160	87%	
• Y	TD Expenses	\$402,109	66%	
CECON				
• Y	TD Revenue	\$190,944		
• Y	TD Expenses	\$134,098		
4.7b Budget v	/ Actual			
General				
Reve	nue			
•	Dues & Allotment	\$310,953	93%	
•	Meetings/Conferences	\$148,259	85%	
•	Publication Revenue	\$5,153	30%	
•	Investment Draw & Other	\$294	1%	
•	Designated	\$14,500	1450%	Not a budgeted item
Expe	nses			
•	Salaries and Services	\$162,201	56%	
•	Meetings/Conferences	\$148,441	80%	
•	Publication Expense	\$2,995	52%	
•	Services	\$48,780	80%	

	Designated	\$0)%				
• /	Admin	\$39,692	64	4%				
CECON								
	Revenue	\$190,944						
	Expenses	\$134,098						
4.7c Statement c	of Financial Position							
General								
	I Assets	\$702,539						
	I Liabilities	\$308,176						
CECON								
	l Assets I Liabilities	\$260,606 \$0						
		ΦΟ						
	oluntary Contributions							
 Income 		\$310,953	93	3%				
4.7e Investments	s as of April 28, 2023							
Edward	Jones Investments	\$465,630	4.	6% YTD				
COMMITTEE Budge	et & Finance Committee			CHAIR	Glenn Goldstein PE			
Discussed T	Rowe Price shareholder	r proxy statemer	nt					
ITEMS FOR AGENDA	ITEMS FOR AGENDA List items requiring action or discussion here.							
No anticipated items	No anticipated items for discussion or action.							

Ronald W. Meyer, P.L.L.C. Certified Public Accountant

401 West 15th Street, Suite 850 • Austin, Texas 78701 • Phone: (512) 476-4511 • Fax: (512) 476-4508 ACCOUNTANT'S COMPILATION REPORT

To the Board of Directors Texas Section - ASCE Austin, Texas

Management is responsible for the accompanying financial statements of Texas Section – ASCE (a nonprofit organization), which comprise the statement of financial position as of April 30, 2023, and the related statement of activities for the one month and seven months then ended, and the accompanying supplementary information for the one month and seven months then ended, which is presented only for supplementary analysis purposes, in accordance with accounting principles generally accepted in the United States of America. We have performed a compilation engagement in accordance with Statements on Standards for Accounting and Review Services promulgated by the Accounting and Review Services Committee of the AICPA. We did not audit or review the financial statements or supplementary information nor were we required to perform any procedures to verify the accuracy of completeness of the information provided by management. Accordingly, we do not express an opinion, a conclusion, nor provide any form of assurance on these financial statements or supplementary information.

Management has elected to omit substantially all of the disclosures and the statement of cash flows required by accounting principles generally accepted in the United States of America. If the omitted disclosures and the statement of cash flows were included in the financial statements, they might influence the user's conclusions about the Association's financial position, changes in net assets, and cash flows. Accordingly, these financial statements are not designed for those who are not informed about such matters.

Management has not reported expenses by natural and functional classification in either the statement of activities, separate statements, or in notes as required by ASU 2016-14, *Not-for-Profit Entities (Topic 958): Presentation of Financial Statements of Not-for-Profit Entities.* Management has not determined the effect of this departure from accounting principles generally accepted in the United States of America on these financial statements.

We are not independent with respect to Texas Section – ASCE.

Austin, Texas June 13, 2023

Texas Section American Society of Civil Engineers Statement of Financial Position (General) April 30, 2023

April 30, 2023		Apr 30, 23			
ASSETS					
Current Assets					
Checking/Savings					
1102 · CHECKING - OPERATING	\$	186,293.52			
1117 · EDWARD JONES INVESTMENTS		465,630.31			
1151 · WF GENERAL BRANCH FUND SVGS		11,849.25			
1153 · INSTITUTE CHAPTER SAVINGS		(29,974.51)			
1153-01 · GI - GEOTECHNICAL INSTITUTE		17,394.71			
1153-02 · EWRI - ENVIRONMENTAL WATER RESOURCES		3,913.90			
1153-03 · CI - CONSTRUCTION		500.00			
1153-04 · SEI - STRUCTURAL ENGINEERING		3,900.00			
1153-05 · T&DI - TRANSPORTATION & DEVELOPMENT		2,000.00			
1153-06 · UESI - UTILITIES ENGINEERING AND SURVEYING		29,101.83			
Total 1153 · INSTITUTE CHAPTER SAVINGS		26,835.93			
1154 · STUDENT SYMPOSIUM SVGS	_	6,777.91			
Total Checking/Savings		697,386.92			
Accounts Receivable					
1190 · ACCOUNTS RECEIVABLE		2,409.62			
Total Accounts Receivable		2,409.62			
Other Current Assets					
1175 · SECURITY DEPOSIT - OFFICE		1,800.00			
1182 · PREPAID POSTAGE - BUSINESS REPLY		1.16			
1310 · RECEIVABLE FROM PORTER FUND		504.54			
2215 · FUNDS HELD FOR MEMORIAL GIFTS		436.59			
Total Other Current Assets		2,742.29			
Total Current Assets		702,538.83			
Fixed Assets					
1210 · FURNITURE AND EQUIPMENT		15,945.13			
1220 · ACCUMULATED DEPRECIATION	_	(15,945.13)			
Total Fixed Assets		-			
TOTAL ASSETS	\$	702,538.83			

Texas Section American Society of Civil Engineers Statement of Financial Position (General) April 30, 2023

Apr 30, 23 **LIABILITIES & NET ASSETS** Liabilities **Current Liabilities Accounts Payable** 83,190.26 2100 · ACCOUNTS PAYABLE \$ **Total Accounts Payable** 83,190.26 **Credit Cards** 7,058.13 2144 · Visa 7,058.13 **Total Credit Cards Other Current Liabilities** 2210 · FUNDS HELD FOR GEN BRANCH FUND 39,635.91 42,010.75 2213 · FUNDS HELD FOR INSTITUTE CHAPTERS 136,281.00 2230 · DUE TO CECON 217,927.66 **Total Other Current Liabilities Total Current Liabilities** 308,176.05 308,176.05 **Total Liabilities Net Assets** 3100 · NET ASSETS WITHOUT RESTRICTIONS 266,269.66 128,093.12 Net Increase/(Decrease) in Net Assets 394,362.78 **Total Net Assets TOTAL LIABILITIES & NET ASSETS** 702,538.83

Texas Section American Society of Civil Engineers Statement of Financial Position (CECON) April 30, 2023

April 00, 2020		Apr 30, 23				
ASSETS						
Current Assets						
Checking/Savings						
1107 · WF CECON	\$	124,324.67				
Total Checking/Savings		124,324.67				
Other Current Assets						
1193 · DUE FROM GENERAL		136,281.00				
Total Other Current Assets		136,281.00				
Total Current Assets		260,605.67				
TOTAL ASSETS	\$	260,605.67				
LIABILITIES & NET ASSETS						
Liabilities						
Total Liabilities	\$	-				
Net Assets						
3100 · NET ASSETS WITHOUT RESTRICTIONS		203,759.17				
Net Increase/(Decrease) in Net Assets	_	56,846.50				
Total Net Assets		260,605.67				
TOTAL LIABILITIES & NET ASSETS						
	\$	260,605.67				

Ν

Texas Section American Society of Civil Engineers Statement of Activities (General) For One Month and Seven Months Ended April 30, 2023

	Apr 23	Oct 22 - Apr 23
Operating Income/Expense		
Income		
DUES AND ALLOTMENT		
4110 · NATIONAL ALLOTMENT	\$ -	\$ 38,967.59
4120 · BRANCH DUES	2,134.00	36,964.00
4130 · SECTION DUES	12,754.6	1 231,915.61
4140 · SECTION VOLUNTARY CONTRIBUTION	60.0	0 3,106.00
Total DUES AND ALLOTMENT	14,948.6	1 310,953.20
SECTION MEETINGS/CONFERENCES		
4211 · STUDENT SYMPOSIUM GENERAL	0.8	6 4.43
4211-23 · STUDENT SYMPOSIUM 2023	8,875.0	0 133,500.00
4215 · LEGISLATIVE DRIVE-IN	-	13,635.00
4410 · TXSX WEBINARS	-	920.00
Total SECTION MEETINGS/CONFERENCES	8,875.8	6 148,059.43
PUBLICATION REVENUE	-,	
4331 · CLASSIFIED ADS TCE/WEB	851.0	0 4,352.85
4331 · OLASSIFIED ADS TOLIVED	-	800.00
Total PUBLICATION REVENUE	851.0	
OTHER REVENUE	001.0	5,152.05
4428 · YOUNGER MEMBER COMMITTEE	200.0	0 200.00
	200.0	294.05
	200.0	00 494.05
		14 500 00
4640 · REGION 6 CONTRIBUTIONS		14,500.00
Total DESIGNATED REVENUE	-	14,500.00
Total Income	24,875.4	7 479,159.53
Expense		
SALARIES AND SERVICES		
5111 · SALARIES	15,541.6	
5112 · PAYROLL TAXES	1,176.1	
5113 · BENEFITS	3,932.6	
5121 · SERVICES - CONSULTING/TEMPS	1,932.5	
5131 · SERVICES - PAYROLL ADMIN	100.0	0 700.00
Total SALARIES AND SERVICES	22,683.0	162,201.32
SECTION MEETINGS/CONFERENCE EXP		
5211-22 · SUPPORT STUDENT SYMPOSIUM 2022	-	15,773.91
5211-23 · SUPPORT STUDENT SYMPOSIUM 2023	103,189.1	4 115,484.83
5211-24 · SUPPORT STUDENT SYMPOSIUM 2024	1,567.0	1,567.05
5215 · LEGISLATIVE DRIVE-IN	10,591.7	11,101.75
5220 · LDW-LEADERSHIP DEVELOPMENT WEEKEND	-	1,104.66
5222 · EXCOMM MEETING	-	360.82
5223 · BOD MEETING EXPENSES	-	1,332.50
5224 · PRESIDENT'S RECEPTION	-	1,715.16
Total SECTION MEETINGS/CONFERENCE EXP	115,347.9	148,440.68
PUBLICATION EXPENSE		
5318 · WEBSITE - MAINTENANCE	418.0	1,954.00
5321 · COMMUNICATIONS SUPPORT	-	1,040.69
Total PUBLICATION EXPENSE	418.0	2,994.69

See accountant's report.

Texas Section American Society of Civil Engineers Statement of Activities (General)

For One Month and Seven Months Ended April 30, 2023

	Apr 23	Oct 22 - Apr 23
SECTION SERVICES		
5511 · BRANCH DUES PASS-THRU	2,134.00	37,008.00
5513 · OFFICERS - TRAVEL/EXPENSES	1,001.47	6,290.70
5514 · MULTI REGION LEADERSHIP CONFERENCE	-	1,155.98
5523 · MEMBERSHIP COMMITTEE	-	736.49
5525 · GOVERNMENT AFFAIRS	-	848.39
5527-10 · STEM COMMITTEE	-	425.10
5528 · YOUNGER MEMBERS COMMITTEE	678.47	2,315.38
Total SECTION SERVICES	3,813.94	48,780.04
SECTION ADMINISTRATION		
5710 · STAFF TRAINING, DUES, SUBSCRIPTIONS	134.25	2,567.27
5711 · RENT	1,800.00	10,800.00
5720 · SECTION OFFICE RELOCATION	45.45	205.72
5721 · PROPERTY TAX	4.57	135.50
5722 · EQUIPMENT FUND & EQUIP/FURN R&M	812.51	7,037.42
5729 · BANK FEES	25.00	266.32
5731 · CREDIT CARD TRANSACTION FEES	281.93	3,539.33
5732 · AUDIT	-	8,000.00
5733 · INSURANCE	-	1,294.00
5734 · OFFSITE STORAGE/ARCHIVES	-	627.00
5735 · STAFF - TRAVEL/EXPENSES	331.84	1,650.64
5736 · MISCELLANEOUS	53.04	835.22
5741 · OFFICE SUPPLIES, SHIPPING, PRINTING	224.21	1,362.74
5745 · EX DIR MARKETING BUDGET	-	9.38
5747 · TELECOMM SVCS (PHONE EMAIL INTERNET)	143.37	1,361.88
Total SECTION ADMINISTRATION	3,856.17	39,692.42
Total Expense	146,119.07	402,109.15
Operating Increase/(Decrease) in Net Assets	(121,243.60)	77,050.38
9510 · DIVIDEND - INVESTMENTS	546.88	13,002.14
9520 · GAIN (LOSS) - INVESTMENTS	4,884.13	38,040.60
Net Increase/(Decrease) in Net Assets	\$ (115,812.59)	\$ 128,093.12

Texas Section American Society of Civil Engineers Statement of Activities (CECON) For One Month and Seven Months Ended April 30, 2023

	Apr 23		Oc	t 22 - Apr 23
Ordinary Income/Expense				
Income				
SECTION MEETINGS/CONFERENCES				
4210 · TX CECON	\$	4,261.48	\$	190,944.30
Total SECTION MEETINGS/CONFERENCES		4,261.48		190,944.30
Total Income		4,261.48		190,944.30
Expense				
SECTION MEETINGS/CONFERENCE EXP				
5210 · TX CECON		643.00		134,097.80
Total SECTION MEETINGS/CONFERENCE EXP	_	643.00		134,097.80
Total Expense		643.00		134,097.80
Net Increase/(Decrease) in Net Assets	\$	3,618.48	\$	56,846.50


TEXAS SECTION-ASCE FINANCIAL SUMMARY (GENERAL) FOR ONE MONTH AND SEVEN MONTHS ENDED APRIL 30, 2023 WITH COMPARISON TO APRIL 2022

		ACTUAL		,			BUDGET			
	2021-2022	2022-2023	2021-2022	2022-2023	2021-2022	2022-2023		2022-2023	2021-2022	2022-2023
	Current			Year-To-				Percent		Budget
Account	Period	Period	Date	Date	Budget	Budget	Realized	Realized	Remaining	Remaining
							(Ideal -	(Ideal -		
							00.00%	0.00.00		
OPERATING REVENUE										
Dues & Allotment	17,426	14,949	301,344	310,953	363,075	334,900	83.00%	92.85%		23,947
SX Mtgs/Confs/Spec Events	2,967	8,876	171,909	148,059	150,200	173,950	114.45%		3	25,891
Publication Revenue	604	851	10,604	5,153	20,000	17,000	53.02%			11,847
Cont Prof Dev Seminar	200	•	200	'	1	ı	%00.0			
Other Revenue	ı	200	28,218	494	63,300	23,300	44.58%		(r)	22,806
Designated Revenue		'	1,000	14,500	2,500	1,000	40.00%	1450.00%	1,500	(13,500)
TOTAL REVENUE	21,197	24,876	513,275	479,159	599,075	550,150	85.68%	87.10%	85,800	70,991
OPERATING EXPENSE										
Salaries & Support	22,765	22,683	130,194	162,201	309,700	291,600	42.04%		179,506	129,399
SX Mtgs/Confs/Spec Events	94,531	115,348	143,376	148,441	164,500	174,500	87.16%			26,059
Publication Expense	497	418	3,774	2,995	6,000	5,800	62.90%		2,226	2,805
Prof Dev Seminar	ı	'	1	'	1	I	%00.0			ı
Section Services	3,723	3,814	42,402	48,780	65,750	60,800	64.49%	~		12,020
Designated Expenses	ı	ļ	925	T	4,925	4,700	18.78%			4,700
Section Administration	6,608	3,856	41,608	39,692	77,710	62,000	53.54%	64.02%	36,102	22,308
TOTAL EXPENSE	128,124	146,119	362,279	402,109	628,585	599,400	57.63%	67.09%	266,306	197,291
OPERATIONAL EXCESS BEVENIEV (EXDENSE)	(106 027)	(121 243)	150 996	77 050	(29.510)	(49.250)				
BUDGET OVEREXPENDED/ (UNDEREXPENDED)									(180,506)	(126,300)

See accountant's report.

•

TEXAS SECTION-ASCE FINANCIAL SUMMARY (GENERAL) FOR ONE MONTH AND SEVEN MONTHS ENDED APRIL 30, 2023



See accountant's report.

TEXAS SECTION-ASCE FINANCIAL SUMMARY (CECON) FOR ONE MONTH AND SEVEN MONTHS ENDED APRIL 30, 2023 WITH COMPARISON TO APRIL 2022

		ACTUAL		Γ			BUDGET			
		2022-2023	2021-2022	2022-2023	2021-2022	2022-2023	2021-2022 2022-2023		2021-2022 2022-2023	2022-2023
	Current	Current	Year-To-	Year-To-	Annual	Annual	Percent	Percent	Budget	Budget
Account	Period	Period	Date	Date	Budget	Budget	Realized	Realized	Remaining	Remaining
							(Ideal - 58.33%	(Ideal - 58.33%		
OPERATING REVENUE										
SX Mtgs/Confs/Spec Events		4,261	7,669	190,944	33,000	45,000	23.24%	424.32%	25,331	(145,944)
TOTAL REVENUE		4,261	7,669	190,944	33,000	45,000	23.24%	424.32%	25,331	(145,944)
OPERATING EXPENSE										
SX Mtgs/Confs/Spec Events	269	643	114,127	134,098	2,750		%00.0	0.00%	(111,377)	(134,098)
TOTAL EXPENSE	269	643	114,127	134,098	2,750		0.00%	0.00%	(111,377)	(134,098)
OPERATIONAL EXCESS REVENUE/ (EXPENSE)) (269)	3,618	(106,458)	56,846	30,250	45,000				
BUDGET OVEREXPENDED/ (UNDEREXPENDED)									136,708	(11,846)

See accountant's report.

Texas Section American Society of Civil Engineers Statement of Activities - Budget vs. Actual (General) For One Month and Seven Months Ended April 30, 2023

	Apr 23	Oct 22 - Apr 23	Budget	Remainder	% Act - Bud
h					
Income DUES AND ALLOTMENT					
4110 · NATIONAL ALLOTMENT	0.00	38,967.59	40,000.00	1,032.41	97.42%
4120 · BRANCH DUES	2,134.00	36,964.00	40,400.00	3,436.00	91.50%
4130 · SECTION DUES	12,754.61	231,915.61	250,000.00	18,084.39	92.77%
4140 · SECTION VOLUNTARY CONTRIBUTION	60.00	3,106.00	4,500.00	1,394.00	69.02%
Total DUES AND ALLOTMENT	14,948.61	310,953.20	334,900.00	23,946.80	92.85%
SECTION MEETINGS/CONFERENCES	8,875.86	148,059.43	173,950.00	25,890.57	85.12%
4331 · CLASSIFIED ADS TCE/WEB	851.00	4,352.85	8,000.00	3,647.15	54.41%
4332 · DIGITAL ADVERTISING	0.00	800.00	9,000.00	8,200.00	8.89%
Total PUBLICATION REVENUE	851.00	5,152.85	17,000.00	11,847.15	30.31%
	0.00	0.00	0.00	0.00	0.00%
OTHER REVENUE					
4428 · YOUNGER MEMBER REVENUE	200.00	200.00	800.00	600.00	25.00%
4510 · INVESTMENT DRAW	0.00	0.00	22,000.00	22,000.00	0.00%
4550 · MISCELLANEOUS	0.00	294.05	800.00	505.95	36.76%
Total OTHER REVENUE	200.00	494.05	23,600.00	23,105.95	2.09%
		t.			
DESIGNATED REVENUE					
4620 · TCEL/SAC	0.00	0.00	1,000.00	1,000.00	0.00%
4640 · REGION 6 CONTRIBUTIONS	0.00	14,500.00	0.00	-14,500.00	0.00%
Total DESIGNATED REVENUE	0.00	14,500.00	1,000.00	-14,500.00	1450.00%
Total Income	24,875.47	479,159.53	550,450.00	70,290.47	87.05%
Expense					
SALARIES AND SERVICES					
5111 · SALARIES	15,541.66	111,779.96	200,000.00	88,220.04	55.89%
5112 · PAYROLL TAXES	1,176.18	8,458.80	15,250.00	6,791.20	55.47%
5113 · BENEFITS	3,932.68	28,004.16	52,650.00	24,645.84	53.19%
5121 · SERVICES - CONSULTING/TEMPS	1,932.50	13,258.40	19,500.00	6,241.60	67.99%
5122 · SERVICES - ARCHIVING	0.00	0.00	3,000.00	3,000.00	0.00%
5131 · SERVICES - PAYROLL ADMIN	100.00	700.00	1,200.00	500.00	58.33%
Total SALARIES AND SERVICES	22,683.02	162,201.32	291,600.00	129,398.68	55.62%
SECTION MEETINGS/CONFERENCE EXP					
5211-22 · SUPPORT-STUDENT SYMPOSIUM 2022	0.00	15,773.91	0.00	-15,773.91	0.00%
5211-23 · SUPPORT-STUDENT SYMPOSIUM 2023	103,189.14	115,484.83	139,000.00	23,515.17	83.08%
5211-24 · SUPPORT-STUDENT SYMPOSIUM 2024	1,567.05	1,567.05	6,000.00	4,432.95	26.12%
5215 · LEGISLATE DRIVE-IN	10,591.75	11,101.75	5,000.00	-6,101.75	222.04%
5220 · LDW-LEADERSHIP DEVELOPMENT WEEKEND	0.00	1,104.66	20,000.00	18,895.34	5.52%
5222 · EXCOMM MEETING	0.00	360.82	1,000.00	639.18	36.08%
5223 · BOD MEETING EXPENSES	0.00	1,332.50	1,500.00	167.50	88.83%
5224 · PRESIDENT'S RECEPTION	0.00	1,715.16	2,000.00	284.84	85.76%
Total SECTION MEETINGS/CONFERENCE EXP	115,347.94	148,440.68	174,500.00	26,059.32	85.07%

Texas Section American Society of Civil Engineers Statement of Activities - Budget vs. Actual (General) For One Month and Seven Months Ended April 30, 2023

Apr 23 Oct 22 - Apr 23 Budget Remainder % Act - Bud PUBLICATION EXPENSE 5318 · WEBSITE - MAINTENANCE 418.00 1,954.00 3,800.00 1,846.00 51.42% 52.03% 2,000.00 959.31 5321 · COMMUNICATIONS SUPPORT 0.00 1,040.69 2,805.31 51.63% 418.00 5,800.00 **Total PUBLICATION EXPENSE** 2,994.69 SECTION SERVICES 3,392.00 91.60% 5511 · BR DUES - PASS THROUGH 2,134.00 37,008.00 40,400.00 106.62% 5513 · OFFICERS - TRAVEL/EXPENSES 1,001.47 6,290.70 5,900.00 -390.70 5514 · MULTI REGION LEADERSHIP CONFERENCE 0.00 1,155.98 2 500 00 1.344.02 46.24% 1,300.00 0.00% 5522 · HONORS COMMITTEE 0.00 0.00 1,300.00 36.82% 5523 · MEMBERSHIP COMMITTEE 0.00 736.49 2,000.00 1,263.51 0.00% 1,500.00 1,500.00 5524 · PAST PRESIDENTS' COUNCIL/OCEA 0.00 0.00 169.68% 5525 · GOVERNMENT AFFAIRS 0.00 848.39 500.00 -348.39 17.00% 425.10 2,500.00 2,074.90 5527-10 · STEM COMMITTEE 0.00 105.24% 5528 · YOUNGER MEMBERS COMMITTEE 678.47 2,315.38 2,200.00 -115.38 0.00 1,000.00 1,000.00 0.00% 5532 · INFRASTRUCTURE REPORT CARD CMTE 0.00 5533 · STRATEGIC PLANNING COMMITTEE 0.00 0.00 1,000.00 1,000.00 0.00% **Total SECTION SERVICES** 3,813.94 48,780.04 60,800.00 12,019.96 80.23% 0.00% 4,700.00 4,700.00 DESIGNATED EXPENSE 0.00 0.00 SECTION ADMINISTRATION 5710 · STAFF TRAINING, DUES, SUSCRIPTIONS 134.25 2,567.27 2,000.00 -567.27 128.36% 21,600.00 10,800.00 50 00% 5711 · RENT 1,800.00 10,800.00 5,000.00 4,794.28 4.11% 5720 · SECTION OFFICE RELOCATION 205.72 45.45 300.00 164.50 45.17% 5721 · PROPERTY TAX 4.57 135.50 5722 · EQUIPMENT FUND & EQUIP/FURN R & M 812.51 7,037.42 9,000.00 1,962.58 78.19% 44.39% 600.00 333.68 25.00 266.32 5729 · BANK FEES 1,060.67 76.94% 5731 · CREDIT CARD TRANSACTION FEES 281.93 3,539.33 4,600.00 5732 · AUDIT 8,000.00 0.00 -8,000.00 0.00% 0.00 106.00 92.43% 1,294.00 1,400.00 5733 · INSURANCE 0.00 48.23% 5734 · OFFSITE STORAGE/ARCHIVES 0.00 627.00 1,300.00 673.00 5743 · STAFF - TRAVEL/EXPENSES 331.84 1,650.64 9,600.00 7,949.36 17.19% 111.36% 750.00 -85.22 5736 · MISCELLANEOUS 53.04 835.22 5741 · OFFICE SUPPLIES, SHIPPING, PRINTING 224 21 1.362.74 2,500.00 1,137.26 54.51% 350.00 340.62 2.68% 5745 · EX DIR MARKETING BUDGET 0.00 9.38 5747 · TELECOMM SVCS (PHN EMAIL INTERNET) 3,000.00 1,638.12 45.40% 143.37 1,361.88 62,000.00 22,307.58 64.02% **Total SECTION ADMINISTRATION** 3,856.17 39,692.42 197,290.85 336.57% **Total Expense** 146,119.07 402,109.15 599,400.00 -157.41% -48,950.00 -126.000.38 **Operating Increase/(Decrease) in Net Assets** -121,243.60 77.050.38 9510 · DIVIDEND - INVESTMENTS 546.88 13,002.14 3,500.00 -9,502.14 371.49% 115.62% 32,900.00 -5,140.60 9520 · GAIN (LOSS) - INVESTMENTS 38,040.60 4,884.13 -100.00 0.00% 5723 · DEPRECIATION EXPENSE -100.00 Net Increase/(Decrease) in Net Assets \$(115,812.59) \$128,093.12 \$(12,650.00) \$(140,743.12) -1012.59%

Texas Section American Society of Civil Engineers Statement of Activities - Budget vs. Actual (CECON) For One Month and Seven Months Ended April 30, 2023

	Apr 23	Oct 22 - Apr 23	Budget	Remainder	% Act - Bud
Income					
SECTION MEETINGS/CONFERENCES	4,261.48	190,944.30	45,000.00	-145,944.30	424.32%
Total Income	4,261.48	190,944.30	45,000.00	-145,944.30	424.32%
Expense					
SECTION MEETINGS/CONFERENCE EXP					
5210 · TX CECON	643.00	134,097.80	0.00	-134,097.80	0.00%
Total SECTION MEETINGS/CONFERENCE EXP	643.00	134,097.80	0.00	-134,097.80	0.00%
Total Expense	643.00	134,097.80	0.00	-134,097.80	0.00%
Net Increase/(Decrease) in Net Assets	3,618.48	56,846.50	45,000.00	-11,846.50	126.33%

ASCE TEXAS SECTION 2022 - 2023 OPERATING BUDGET

				FY23		
					% of Budget	
		AMENDED	ADOPTED	ACTUAL	REALIZED	NOTES
		BUDGET	BUDGET	as of	as of	
		2022-2023	2022-2023	4/30/2023	4/30/2023	
	Reconciliation Status:			CPA		
	REVENUES					
	ALLOTMENT DUES VOL DONATION					
4110	NATIONAL ALLOTMENT	40,000	40,000	38,968	97%	Typically received in December/January
4120	BRANCH DUES	40,400	40,400	36,964	91%	pass-through
4130	SECTION DUES	250,000	250,000	231,916	93%	# of Subscribing Members x Sec Dues; Section dues increase 2024+
4140	SECTION VOLUNTARY CONT	4,500	4,500	3,106	69%	
	TOTAL, ALLOTMENT DUES VOL DONATION	334,900	334,900	310,953	93%	Fall 2022 membership sweepstakes; addt'l drive ideas, including email/letter to new PE (get TBPE List); FY2
	SX MTS/CONFS/SPEC EVENTS					
4210	TX CECON (SUPPORT & PROFIT SHARING)	36,000	36,000		0%	annual commitment for staff time used (stair step up \$6k in 2023, then \$9k to \$45k in 2024); \$2,750/yr fo
4211	STUDENT SYMPOSIUMS (GENERAL)	10,000	10,000	4.43	0%	Revenue covers expenses at 5211 less support
4211-21	STUDENT SYMPOSIUM 2021 (UT Austin)					
4211-22	STUDENT SYMPOSIUM 2022 (U of Houston)					
4211-23	STUDENT SYMPOSIUM 2023 (WT & TTU)	145,000	145,000	133,500	92%	
4212-21						
4215	LEGISLATIVE DRIVE-IN	1,750	1,750	13,635	779%	FY18-19 assume 50 attendees @ \$20/ea; FY19-20 no event planned; FY20-21 assume 75 attendees @ \$25,
4221	OTHER CONFERENCES	1,200	1,200		0%	FY17-18 I Week - Harvey Panel & Rpt Release; FY18-19 & FY19-20 I Week Event; FY20-21 I Week and/or IR
4428	YOUNGER MEMBER COMMITTEE	500	500	200	40%	camping trip
4410	TX SX WEBINARS	16,000	16,000	920	6%	FY21-22 sponsorship test; FY22-23 tiered pricing + sponsorships; Reminder: Increase Webinar Marketing, L
	TOTAL, SX MTS/CONFS/SPEC EVENTS (w/o 4210)	174,450	174,450	148,259	85%	
	PUBLICATIONS/COMMUNICATIONS REVENUE	-				
4331	CAREER CENTER	8,000	8,000	4,353	54%	Career Center sales
4332	DIGITAL ADVERTISING (NEWSLETTER & WEB)	9,000	9,000	800	9%	FY22-23 began 3rd party sales in Feb; FY18-19/FY19-20 TCE print to 100% online; FY20-21/21-22 staff drive
	TOTAL, PUBLICATIONS/COMMUNICATIONS REVENUE	17,000	17,000	5,153	30%	(Note FY18-19 revenue drops as well as expenses for TCE print production)
	OTHER REVENUE					
4510	INVESTMENT DRAW	22,000	22,000		0%	FY22-23 reduce to recom 5% only; FY17-18 Website (\$10k) IRC Support (\$5k); FY18-19 TCE Digital (\$5k) Ba
4540	GENERAL BRANCH FUND DRAW	22,000	22,000		070	FY22-23 work to repay "loans"; FY18-19 1/2 LDW (\$6,750) & 2 MRLC reg (\$300/ea); FY20-21 1/2 LDW (\$6,
4540 45XX	STUDENT SYMPOSIUM SAVINGS DRAW					FY21-22 repaid "loans"; Funds for atypical expenses like lake venue rental, not be covered by sponsorships
						rtz1-zz repaid libans ; runus for atypical expenses like take venue rental, not be covered by sponsorships
4530				204	270/	
4550		800	800	294	37%	Includes credit card "cash back" rewards (note: card requires \$75 annual fee)
4231	MERCHANDISE SALES TOTAL, OTHER REVENUE	22,800	22,800	294	1%	net sales (less tax); FYs17-19 books sales; FYs19-23 merch sales not anticipated
	TOTAL, OTHER REVENUE	22,800	22,800	234	170	
	DESIGNATED REVENUE					
4620	TCEL GIFT FOR STUDENT COMP. AWARD	1,000	1,000		0%	Student Tech Paper Prize Funds; FY18-19 TCEL will increase their support from \$700 to \$1K
4630	GRANTS			14,500	NB	Committee Grants (GAC, STEM, YM); FY20-21 combine 4630, 4635, 4640, & 4650
	TOTAL, DESIGNATED REVENUE	1,000	1,000	14,500	1450%	
	TOTAL REVENUES	550,150	550,150	479,160	87%	

; FY23-24 S/B dues increase

r for Staff Travel; \$0k 2020-22 profit share

\$25/ea; 2023 tiered reg or IRC Release

ng, Leverage Institute Chapter Webinar MOU

riven

k) Balance Budget (\$31.5k); FY19-20 (\$35K) Balance Budget (\$6,750) & 2 MRLC reg (\$300) ships; FY21-22 20' steel storage container

ASCE TEXAS SECTION 2022 - 2023 OPERATING BUDGET

				FY23		
				F123	% of Budget	
				ACTUAL	% of Budget	
		AMENDED	ADOPTED	ACTUAL	REALIZED	NOTES
		BUDGET	BUDGET	as of	as of	
	Deservitietien Chatra	2022-2023	2022-2023	4/30/2023	4/30/2023	
	Reconciliation Status:			CPA		
	EXPENSES					
	SALARIES & SUPPORT					
5111	SALARIES & SUPPORT SALARIES-GROSS	200,000	200,000	111,780	56%	3 FTEs (ED, Communications Specialist, Operations Specialist) 1 PTE (summer intern 15 hrs/wk, 12 wks)
5112	SALARIES-OROSS	15,250	15,250	8,459	55%	Note: FY19-20 avg. 12% of Gross Salary; FY20-21 avg. 8% of Gross Salary
5112	SALARIES JOE SEC	52,650	52,650	28,004	53%	FY19-20 avg. 27.5% of Gross Salary; FY20-21 avg. 38% of Gross Salary
5113	SERVICES-CONSULTING/TEMPS	19,500	19,500	13,258	68%	FY20-21 CPA (\$1,100/mo) plus \$1,500 for audit support, IT (\$500/mo); FY21-22 CPA (\$1,100/mo), IT (\$525
5122	SERVICES-ARCHIVING	3,000	3,000	13,230	0%	FY22-23 grant(s) to resume digitizing remaining records
5122	SERVICES PARENTING	1,200	1,200	700	58%	\$100/mo for TSPE payroll processing; FY21-22 mgmt company switch admin fees
5151	TOTAL, SALARIES & SUPPORT	291,600	291,600	162,201	56%	2100/monor Hard El payron processing, 1121 22 mg/m company switch admininees
	TO TAL, SALARILS & SOTT ORT	251,000	291,000	102,201	50%	
	SX MTGS/CONFS/SPEC EVENTS					
5210	TX CECON					CECON Account (7248) = \$98,840 as of 6/22/18. \$87,889.90 as of 04/30/2019; FY19-20 \$2750 for Staff Tra
5211	SUPPORT-STUDENT SYMPOSIUM					FY19-20 \$5k TS financial support, \$75k covered by revenue (4211);
5211-21	STUDENT SYMPOSIUM 2021 (UT Austin)					
5211-22	STUDENT SYMPOSIUM 2022 (U of HOUSTON)			15,774	NB	
5211-23	STUDENT SYMPOSIUM 2023 (WEST TX A&M)	139,000	139,000	115,485	83%	2022+ move to larger Regional conference; post-pandemic overall costs increase
5211-24	STUDENT SYMPOSIUM 2023 (ANGELO STATE)	6,000	6,000	1,567	26%	FY22-23 Assume deposit will be required for venue(s) + any applicable Steel Container annual expenses
5215	LEGISLATIVE DRIVE-IN	16,000	5,000	11,102	69%	FY18-19 estimate 个expenses due to 个attendance; FY20-21 estimate 个expenses due to 个attendance
5220	LEADERSHIP DEVELOPMENT WEEKEND (LDW)	20,000	20,000	1,105	6%	Annual LDW Event (25-50% funding provided by General Branch Fund); FY20-21 budget increase post-pan
5221	OTHER CONFERENCES					misc unplanned activities; FY17-18 Week & Harvey Report Release; FY19-20 Week; FY20-21 IRC Release
5221-03	CORPUS CHRISTI BRANCH MEETINGS					
5222	EXCOMM MEETING (INCLUDES AV)	1,000	1,000	361	36%	January and Summer - \$500/ea; Includes: room rental, food, AV; FY22-23 post-pandemic f&b costs increa
5223	BOARD MEETING (INCLUDES AV)	1,500	1,500	1,333	89%	Symposium and CECON - est \$1,250/ea; Includes: room rental, food, & limited AV; FY22-23 post-pandemi
5224	PRESIDENTS RECEPTION (@ MTGS)	2,000	2,000	1,715	86%	Symposium, Leadership Dev. Wknd, & CECON - est \$1,250/ea; includes: room rental & food; FY22-23 pos
5240	ASCE CONFERENCE CONTRIBUTION					2023 TDI in Aus, annual OTC in Hou; FY18-19 \$1K MRLC Dallas, \$1k National Student Steel Bridge Comp (L
	TOTAL, SX MTGS/CONFS/SPEC EVENTS (w/o 5210)	185,500	174,500	148,441	80%	
	DUDUCATIONS /COMMUNICATIONS EVDENCE					
5230-05	PUBLICATIONS/COMMUNICATIONS EXPENSE HISTORY BOOK					
5250-05	WEB SITE-MAINTENANCE	3,800	3,800	1,954	51%	Hosting \$500/yr & Support \$175/mo, plus \$2-4k misc support tasks for website & TCE subsite
5318	WEB SITE-UPGRADES	3,800	3,800	1,994	51/6	Website Redesign
5321	COMM SUPPORT	2,000	2,000	1,041	52%	Buffer (\$144/yr), Adobe Creative Cloud (\$82/mo), Zoom meeting (\$550/year), Dropbox (\$130/yr), Canva (
5521	TOTAL, PUBLICATIONS/COMMUNICATIONS EXPENSE	5,800	5,800	2,995	52%	
	· , · · · · · · · · · · · · ·	-,	-,	,		
	SECTION SERVICES					
5511	BR DUES-PASS THRU	40,400	40,400	37,008	92%	cancels out 4120
5513	OFFICERS-TRAVEL/EXPENSES	5,900	5,900	6,291	107%	est 50% of Pres, Pres-E, Past P, and VP Pro travel; see corresponding tab
5514	MULTI REGION LEADERSHIP CONFERENCE	2,500	2,500	1,156	46%	\$300/person reg fee. Send 4 annually (ED, Pres Elect, Pres, YM Chair), send more and all staff in held in Te
5521	HISTORY COMMITTEE					Coming soon: Rt 66 marker; FY15-16 \$300 EP bound. marker; FY17-18 Dallas Old Red Courthouse Centenr
5522	HONORS COMMITTEE	1,300	1,300		0%	Increase budget by \$1,600 if/when Lifetime Service Awards will be presented (every 5 years, next = 2023 l
5523	MEMBERSHIP COMMITTEE	2,500	2,000	736	29%	FY16-17 STAY Grant; FY18-19 Social Media Mktg, CECON Registration giveaways, etc.; FY19-20 used for CE
5524	PAST PRES. COUNCIL/OCEA	1,500	1,500		0%	FY17-18 Cast Bronze Plaque ~\$1,250 + \$150 for wood plaque
5525	GOVERNMENT AFFAIRS	500	500	848	170%	\$125/yr online TX Leg db subscription; FY17-18 \$500 GA Business Cards; FY18-19 \$500 biz cards & \$500 Ti
5526	STUDENT ACTIVITIES CMTE					student activity chair or head judge new comp needs, etc, adjustment from prior year lessons learned; Pri
	STEM CMTE	2,500	2,500	425	17%	FY16-17 UEF grant denied; FY17-18, FY18-19 & FY19-20 \$1K for TAME STEM Comp Support & \$1.6K for St
5528	YOUNGER MEMBERS CMTE	2,200	2,200	2,315	105%	For MRLC registration (\$300) & Camping Trip; FY22-23+ increased travel w/ new branded tent + promo ac
5529	OTHER COMMITTEES					FY18-19 \$2,000 for Institute Chapter Mtgs & Travel; FY19-20 \$200 for Misc Travel or Recruitment Activitie
5532	INFRASTRUCTURE REPORT CARD CMTE	1,000	1,000		0%	FY19-20 Materials & 2021 IRC Prep (Consultant ~\$10k; mailing survey to local government ~\$1.5k); FY20-2
5533	STRATEGIC PLANNING CMTE	1,000	1,000	40 700	0%	market/socialize current plan; FY20-21 funding for meetings (2 in-person \$2,500/ea), \$500 printing/produ
	TOTAL, SECTION SERVICES	61,300	60,800	48,780	80%	
	DESIGNATED EXPENSE					
5620	TCEL GIFT FOR STUDENT COMP. AWARD	1,200	1,200		0%	Tech. Paper Prize awards equal TCEL donation at 4260: \$600 - 1st, \$300 - 2nd, \$100 - 3rd
5622	KEITH MCBRIDE SPIRIT of COMP. AWARD	500	500		0%	\$125 plaque + \$300 prize money;-FY18-19 Canoe & ???; FY19-20 Canoe Only; discontinued 2022+ when w
5625	SAC CHR & COMP COORD TRAVEL ALLOT	2,000	2,000		0%	Suggest Stipend for Student Activities Cmte Chair & Comp Coord. to attend Student Symposium [\$1k Trav
5635	GRANTS (OTHER ASCE)	2,000	2,000		070	Record expense at committee level
5650	GRANTS (NON-ASCE)					Record expense at committee level
5660	GIFTS - MEMORIAL/OFFICER APPREC/OTHER	1,000	1,000		0%	Gifts/Donations honoring leaders who have passed; FY19-20 Combine w/ 5560; Gift for Immediate Past Pr
	TOTAL, DESIGNATED EXPENSE	4,700	4,700	0	0%	

525/mo)

Travel & Registration

pandemic; FY22+ approved to \$18k ease; FY21-22 Beyond Storms report release; GL TBD: TripBuilder Media Multi Event

crease emic f&b costs increase post-pandemic f&b costs increase p (UTEP); FY19-20 In-kind w/ ASCE Pipelines 2020

va (\$15/mo), Issuu (\$54/mo) + Any creative asset licensing (iStock, Shutterstock, Adobe,

n Texas; FY21-22 virtual; FY22-23 Denver tennial Plaque \$1.5k; FY18-19 \$500 TSHA Annual Mtg Sponsor 123 but presented in 2020 instead) r CECON Raffle Prizes & Printed Materials

00 Travel/Training/Recruiting; FY21-22 increased rep mtgs = travel & handouts ; Prior new buoys, equipment, shirts or other needs ir State STEM Conference; FY22-23 restore to previous activity with new active Chair o activities at Section & Regional events vities 20-21 Materials (\$2.5k), Consultant (\$1k), PR Firm (\$3k); next FY2023-25 oduction, \$2k facilitator

n went Regional, can be used toward other Spirit related award ravel (x2)] be built into Symposium Budget

t Pres. (TCE?); FY21-22 ordered more Past Pres pins

ASCE TEXAS SECTION 2022 - 2023 OPERATING BUDGET

			FY23		
				% of Budget	
	AMENDED	ADOPTED	ACTUAL	REALIZED	NOTES
	BUDGET	BUDGET	as of	as of	
	2022-2023	2022-2023	4/30/2023	4/30/2023	
Reconciliation Statu	s:		CPA		
SECTION ADMIN	Ī				FY21-22: TSAE (\$395 (1st) + \$275 (2nd)), ASCE (\$325 ED)
5710 STAFF TRAINING, DUES, SUBSCRIPTIONS	2,000	2,000	2,567	128%	\$650/FTE: Cont. Ed. (\$40-\$75 per webinar) & Conference (\$400 + travel); FY22-23: 3 FTEs; prior to 2023 \$
5711 RENT	21,600	21,600	10,800	50%	FY22-23 new office \$1800 all in> see new office lease for annual increases; Prior monthly base rent = \$2
5720 SECTION OFFICE RELOCATION	5,000	5,000	206	4%	Lease ends 9/30/22; Office move sept/oct 2022
5721 PROPERTY TAX	300	300	136	45%	FY19-20 est \$325 TCAD + \$150 for copier; FY20-21 & FY21-22 est \$450 TCAD + \$150 for copier
5722 EQUIPMENT FUND & EQUIP/FURN R & M	9,000	9,000	7,037	78%	Copy Machine (\$150/mo), Computer lease (\$400/mo), Office 365 , etc (\$85/mo), QuickBooks (\$915/yr), M
5729 BANK FEES	600	600	266	44%	Electronic Transfer for Branch Dues Pass Through and other EFT enabled payments @ $3/$ Transaction + \$:
5731 CREDIT CARD TRANS FEES	4,600	4,600	3,539	77%	Credit Card Processing Fees
5732 AUDIT			8,000	NB	Section Office is audited every 5th year by contracted 3rd Party; FY 20-21 (total TBD); FY15-16 audit was \$
5733 INSURANCE (B & L)	1,400	1,400	1,294	92%	Hartford Policy Annual Premium, Includes Biz Personal Prop. & Liability, & Personal Injury; increases ~\$50
5734 OFFSITE STORAGE/ARCHIVES	1,300	1,300	627	48%	archive secure storage \$105/mo
5735 STAFF-TRAVEL/EXPENSES	9,600	9,600	1,651	17%	ED: 8 Branches, Fly-In & regional mtgs; All Staff: Leadership Wknd, Site Visits - Doesn't include CECON (See
5736 MISCELLANEOUS	750	750	835	111%	Food/Coffee for Staff meetings & Holiday Dinner
5741 OFFICE SUPPLIES, SHIPPING, PRINTING	2,500	2,500	1,363	55%	Toner, Paper, bottle water srvc, supplies, Stamps, shipping, copy machine overages, biz cards, etc.; FY19-2
5745 EX DIR MARKETING BUDGET	350	350	9	3%	Cover costs of meeting with potential partners/collaborators, and potential members/volunteers
5747 TELECOMM SVCS (PHN EMAIL INTERNET)	3,000	3,000	1,362	45%	Spectrum Internet (\$130/mo), LinkedPhone (\$17/mo for ED Cell Phn), Teams phone (\$??/mo for 3 lines),
TOTAL, SECTION ADMIN	62,000	62,000	39,692	64%	
TOTAL EXPENSES	610,900	599,400	402,109	66%	
OPERATIONAL EXCESS REV (OR EXP)	(60,750)	(49,250)	77,050		
OPERATIONAL EXCESS REV (OR EXP)	(60,750)	(49,250)	77,050		

	INVESTMENTS	AMENDED BUDGET 2022-2023	ADOPTED BUDGET 2022-2023	ACTUAL as of 4/30/2023	% of Budget REALIZED as of 4/30/2023	NOTES
9510	DIVIDEND - INVESTMENTS	3,500	3,500	13,002	371%	
9520	GAIN (LOSS) - INVESTMENTS	32,900	32,900	38,041	116%	
5723	DEPRECIATION EXPENSE	(100)	(100)		0%	
	NET INCREASE (DECREASE) IN NET ASSETS	(24,450)	(12,950)	128,093	-524%	

Legend NB Not budgeted

23 \$1k/FTE = \$2,332+OpEx(\$110/mo)

r), Misc./unplanned equip. (\$500) + \$10/mo fee to use EFT services

/as \$7,500 \$50/yr

(See 5210) or Symposium Registration (See Symposium Budget)

'19-20 Combined w/ 5742 & 5743

es), ED cellphone allowance (\$50/mo); FY19-20 Combined w/ 5744

FORM F-2		0	FFICER REP	ORT
	Agenda Item Number	5.8	Item Title	Directors at Large
	Date	07/21/23	Reported by	Marita Moya PE
	Purpose	Summer 2022-2023	3 Executive Com	mittee Meeting

OFFICER ACTIVITIES

- Recurring Editorial Committee monthly meetings with the Directors at Large, President and President Elect, additional volunteer committee members, and Stephanie Ludlow to discuss TCE content.
 - Utilizing updated article spreadsheet to enable more efficient tracking of content
 Supplying content for every other week TCE releases
 - Continue to encourage social media engagement to promote TCE and other Section program
- Coordinating with Editorial Committee to improve outreach to universities to reach professors and graduate/research students to provide content to TCE and engage this niche membership group
- Help promote Section primary programming utilizing Texas Civil Engineering (TCE) Magazine
 - Texas Civil Engineering Conference (CECON) (Promoting Fall 2023)
 - ASCE Region 6 Student Symposium (Highlighting Spring 2023 Symposium)
 - Legislative Drive-in (Highlighting Spring 2023 Drive-In)

COMMITTEE	Tellers Committee	CHAIR	Michael Gurka PE
Ratified 2	2023-2024 election results to be presented onsite.		
ITEMS FOR AGEND	Α		
Endorse 2023-24	TexASCE officer election results		
Share new article	e & social media content and ideas to <pre>share@texasce.o</pre>	<u>rg</u>	

FORM F-2		OI	FFICER REF	PORT
	Agenda Item Number	6.1	Item Title	Executive Director
	Date	0/7/21/23	Reported by	Jenni Peters, CAE
	Purpose	Summer 2022-202	3 Board of Direc	tion Meeting

REPORT	Staffing and Office Space		
streamlining t am guiding th workload. Co	n has continued to support our volunteers and Section prog he Section records to improve workflow while reducing our e team in volunteer and project best practices, evaluating r ntinuing to evaluate program ROI (return on investment) the uset discussions.	digital footprin new projects ar	t across our platofrms. I nd ideas in relation to
resource and	ort our active volunteer committees continue to utilize the S the number of "access hurdle" reports has declined. Any is s will continue to be shared during meetings.		
REPORT	Communications and Marketing		
Member com	pecialist Mike Sosa continued his renewal communication emunications, tied to getting new subscribing Section memb membership cycle. Communication engagement results w Meeting.	ers engaging i	n their membership
analytics for t social media, A few highligh 1. TCE 2. The r a	ons Specialist Stephanie Ludlow prepared a communication he TexASCE.org website, the Section newsletter, Texas Ci and event app. hts from the report: articles the biggest draw the second quarter of the year new email newsletter has proven to drive more viewers than . Ad sales has picked up, reflected in the corresponding b dln continues to be our most engaged social platform	vil Engineer (T	CE) digital magazine, format
communicatio	Section dues increase taking affect with renewals beginning ons have begun to current members, reminding them how the of all the Section and Branch programs, benefits, and reso	hese additiona	I dues make the
REPORT	Budget and Non Dues Revenue Streams		
advertising sa	primary sources of non-dues revenue continue to include ales, and 3) administrative support of events like Student Sy FY, the Section's Webinar Series may need to be looked at	mposium and	CECON. At the end of
larger pool of	ter, a third-party service began selling website and newslet potential supporters and dedicated sales staff to grow our bear fruit, tipping the digital advertising budgeted revenue	"media kit" offe	rings. This partnership
I will begin to	work with Treasurer Glenn Goldstein in drafting the 2023-2	024 budget as	he meets with officer

REPORT	Other activities	
	er Election: With the election occurring June 1-30, Mike S	0

coordinating, and marketing Election Guideline activities, while monitoring the overall number of subscribing member ballots cast. With a contested election Rules of Operation processes in place (which hasn't occurred in many years), Society general counsel and global election rules have been consulted, used to guide Section's rules and process along the way. See the Past President's and Director-at-Large/Teller reports for details and results.

Branch & Community Outreach: As my role as Executive Director has progressed, I attend industry, Society, Regional, Branch, & Section activities to promote membership and Section activities, while meeting and developing relationships with members and partners. Most recently, I attended OTC and Houston Branch's related dinner reception, Region 6 Symposium, Austin Branch annual Conference, CEO/Volunteer Leader Workshop, ASCE ICTD & Pavements Conference, and TxAPWA's annual conference. Additional opportunities are in the works for the remainder of the year.

Texas Alliance for Minorities in Engineering (TAME): The Texas Section STEM Committee typically supports the annual TAME State STEM Competition via a small sponsorship. I introduced the STEM Committee Chair to this partnership to evaluate the sponsorship and he agreed to continue the Section's support with a \$1000 program sponsorship for their 2023 event. See STEM Committee report in the VP Educational report for more details.

I will continue collaboration with TAME's Executive Director to discuss new volunteer opportunities for future collaborations between our organizations.

CECON Support: As part of my work to help maintain and establish relationships with other professional societies and industry partners, I am working to secure CECON 2023 Collaborators. To date, the 2023 Collaborators include Texas Contractor, TxAPWA, TWDB, Infraday Texas 2024, and PUCT. Please let me (jpeters@texasce.org) know if you have any additional suggestions for potential Collaborators who may be willing to provide in-kind marketing for our flagship annual conference.


ITEMS FOR AGENDA

ASCE Texas Section

Communications Report for July 2023 Board Meeting

Stephanie Ludlow, Communications Specialist

<u>Website</u> (March 2023 –June 2023) During the second quarter of the year, our website had a 30% decrease in pageviews likely due to the Student Symposium concluding. The website received 34,215 unique pageviews during the second quarter of the year. The strongest draw for traffic on the website are *TCE* articles, receiving more than 27% of pageviews.



2. Section Newsletter and Texas Civil Engineer (TCE) digital magazine (YTD)

The new newsletter (Multiview) has proven to yield a higher open rate than Constant Contact. Our open rate is an astonishing 80% compared to 38% with Constant Contact. Individual newsletter readership has increased, with an average of 4,700 unique readers per issue and about 8,500 total opens per issue. We have reaped the benefits from higher readership in our ad sales as well, with an average of \$5,503 per month in ad sales packages. The partnership with a third-party vendor has thus far proved its worth.

Our readership of the TCE has fallen slightly, we predict is due to the newsletter containing more information than a dedicated email featuring just TCE articles. When articles are featured at the top of the newsletter, they receive the most readership. As members and subscribers get used to seeing the new newsletters in their inbox (making tweaks along the way to improve views), we anticipate an increase in TCE article engagement.

- Top 4 viewed articles:
 - 1. Lightweight Cellular Concrete (567 pageviews)*
 - 2. <u>An Update on the TWDB's Texas-Sized State and Regional Flood Planning Effort</u> (251 pageviews)*
 - 3. Adhesive Anchors (198 pageviews)*
 - 4. <u>Mapping Out the Old San Antonio Road</u> (172 pageviews)
 - * Technical Feature

3. Social Media

We have 2,084 followers on LinkedIn. LinkedIn continues to be our most active social media platform. We are on track to meet our goal for 2023 of 2500! In the last 30 days, we added 55 new followers and had over 6,000 post impressions.

• Top 3 Posts on LinkedIn:

- 1. CECON ADS Sponsorship 563 Impressions
- 2. CECON JPH Land Surveying Sponsorship 481 Impressions
- 3. Student Symposium LeTourneau University 377 Impressions

4. Event App

Mobile device event apps during Student Symposium and CECON are well-utilized vehicles for communication for attendees. During the Student Symposium, 71% of attendees downloaded the app, averaging 39.6 clicks per user. The app houses contact and description information for sponsors, exhibitors, and speakers and proves to be a win-win for our supporters and attendees.

FORM F-2		SECTION OFFICE REPORT								
	Agenda Item Number	6.2	Item Title	Operations						
TEXAS SECTION	Date	07/21/23	Reported by	Mike Sosa						
	Purpose	Summer 2022-2023 Executive Committee Meeting								

REPORT	Annual Reports
Annual re	ports – no updates for Summer 2023.
REPORT	Tax Returns
FY 2021-2	022 returns were due February 15, 2023 unless an extension request was filed prior to that date.
The follow	ing Large Branch tax returns are still outstanding:
	ustin - filed extension request and submitted to ASCE for review, on track to be submitted before adline.
wrap up th accordingly	Section's CPA, Ron Meyer, filed an extension request with IRS due to the Texas Section needing to e current audit process. Since then, the audit has finished, and the draft Form 990 has been updated y. The form was provided to the Executive Director, Board of Direction, and ASCE Finance Dept for d comment on May 19, 2023. The form was submitted to the IRS on May 24, 2023.
	nce, tax returns are reported on the year that begins the fiscal year (Oct. 2022) and ends (Sept. 2023). Returns a months after the close of each fiscal year (February 15).
REPORT	Subsidiary Bylaws
Recomme	nded for approval: Fort Worth Branch
The follow	ing bylaws may need to be updated after coordinating with the appropriate leaders:
• Ca	aprock, Central Texas, High Plains
Current St	atus (branch name – date of last bylaws approval – branch dues rate)
 Br. Ca Ca	stin - 04/12/2018 - \$10 $azos - 03/05/2020 - 10 $aprock - 05/14/2011 - 6 entral Texas - 06/02/2001 - \$6 orpus Christi - 09/25/2020 - \$10 allas - 11/07/2012 - \$10 Paso - 04/12/2018 - \$10 ort Worth - 04/20/2006 - \$10 gh Plains - 11/24/2003 - \$6 ouston - 05/06/2019 - \$10 ortheast Texas - 03/05/2020 - \$10 o Grande Valley - 07/09/2021 - \$10 an Antonio - 10/07/2010 - \$10 outheast Texas - 03/05/2020 - \$10 est Texas - 04/12/2018 - \$10
Note: sam request.	ple Texas Section subsidiary bylaws are available for both Branches and Institute Chapters upon

REPORT	Section Meetings Schedule
--------	---------------------------

https://www.texasce.org/events/

ITEMS FOR AGENDA

Consent Agenda 4.1.5 – Approve updates to Fort Worth Branch Bylaws

Agenda Item Number 6.3 Item Title Trust Funds Date 07/21/23 Reported by Jenni Peters CAE Purpose Summer 2022-2023 Executive Committee Meeting Joseph Minor PE Curits Beitel PE TCEF (Foundation) Trustees: Joe Minor PE, Curits Beitel PE, Dick Furlong PE, Tim Newton PE, Jack Furlong PE, Dan Harman PE, Larry Goldberg PE, Ricky Bourque PE, Audra Morse PhD PE, Brian Manning PE, and Travis Attanasio PE (Ex-Officio) TCEF Trustees last met virtually March 16, 2023. An in-person meeting is planned for late-September during CECON. TCEF is under an agreement with the ASCE Texas Section to manage an online presence including a donation form. This new Foundation landing page and online donation form is live at www.TexASCE.orgitoef. Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund bala	FORM F-2										
Purpose Summer 2022-2023 Executive Committee Meeting Texas Civil Engineering Foundation (TCEF) Joseph Minor PE Curtis Beitel PE TCEF (Foundation) Trustees: Joe Minor PE, Curtis Beitel PE, Dick Furlong PE, Tim Newton PE, Jack Furlong PE, Dan Harman PE, Larry Goldberg PE, Ricky Bourque PE, Audra Morse PhD PE, Brian Manning PE, and Travis Attanasio PE (Ex-Officio) TCEF Trustees last met virtually March 16, 2023. An in-person meeting is planned for late-September during CECON. TCEF is under an agreement with the ASCE Texas Section to manage an online presence including a donation form. This new Foundation landing page and online donation form is live at www.TexASCE.org/toef. Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund • TCEF's Texas Section Past Presidents Educational Trust Fund • TOEF's Texas Section Past Presidents IEducational Trust Fund • Tustees: Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio			6.3	Item Title	Trust Funds						
REPORT Texas Civil Engineering Foundation (TCEF) Joseph Minor PE Curtis Beitel PE Curtis Beitel PE Dick Furlong PE, Tim Newton PE, Jack Furlong PE, Dan Hartman PE, Larry Goldberg PE, Ricky Bourque PE, Audra Morse PhD PE, Brian Manning PE, and Travis Attanasio PE (Ex-Officio) TCEF Trustees last met virtually March 16, 2023. An in-person meeting is planned for late-September during CECON. TCEF is under an agreement with the ASCE Texas Section to manage an online presence including a donation form. This new Foundation landing page and online donation form is live at www.TexASCE.org/tcef. Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 1021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 1021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund Thetal PE. Current trusteres terms were extended to through 2022 an		Date	07/21/23	Reported by	Jenni Peters CAE						
REPORT Curris Beitel PE TCEF (Foundation) Trustees: Joe Minor PE, Curris Beitel PE, Dick Furlong PE, Tim Newton PE, Jack Furlong PE, Jank Harman PE, Larry Coldberg PE, Ricky Bourque PE, Audra Morse PhD PE, Brian Manning PE, and Travis Attanasio PE (Ex-Officio) TCEF Trustees last met virtually March 16, 2023. An in-person meeting is planned for late-September during CECON. TCEF is under an agreement with the ASCE Texas Section to manage an online presence including a donation form. This new Foundation landing page and online donation form is live at www.TexASCE.org/tcef. Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. 2021 Form 10, 2023 are 203 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. Fun		Purpose	Summer 2022-202	23 Executive Con	nmittee Meeting						
TCEF (Foundation) Trustees: Joe Minor PE, Curtis Beitel PE, Dick Furlong PE, Tim Newton PE, Jack Furlong PE, Dan Hartman PE, Larry Goldberg PE, Ricky Bourque PE, Audra Morse PhD PE, Brian Manning PE, and Travis Attanasio PE (Ex-Officio) TCEF Trustees last met virtually March 16, 2023. An in-person meeting is planned for late-September during CECON. TCEF is under an agreement with the ASCE Texas Section to manage an online presence including a donation form. This new Foundation landing page and online donation form is live at www.TexASCE.org/tcel. Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees term limited members in 2024. Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. <td>REPORT Texa</td> <td>as Civil Enginee</td> <td>ring Foundation (T</td> <td>CEF)</td> <td></td>	REPORT Texa	as Civil Enginee	ring Foundation (T	CEF)							
GECON. TCEF is under an agreement with the ASCE Texas Section to manage an online presence including a donation form. This new Foundation landing page and online donation form is live at www.TexASCE.org/tcef . Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund • TCEF's Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. • Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. Whi	PE, Dan Hartman F	É, Larry Goldbe			long PE, Tim Newton PE, Jack Furlong						
form. This new Foundation landing page and online donation form is live at www.TexASCE.org/tcel. Marketing to solicit donations is being planned. Check & Savings balance as of June 20, 2023 = \$5,800.69 Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORI John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Felowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.		t met virtually Ma	rch 16, 2023. An in-	person meeting i	is planned for late-September during						
Tax Status: No updates. 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund • TCEF's Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. • Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.	form. This new Fou	ndation landing	bage and online don								
 2021 Form 990-N was submitted in IRS by CPA Ron Meyer on January 17, 2022. Future filings will occur every three years. Annual Report: No updates. The 2023 report will be completed in August prior to the Fall Board of Direction meeting during CECON. Texas Section Past Presidents Educational Trust Fund TCEF's Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.	Check & Savings	balance as of Ju	ne 20, 2023 = \$5,80	0.69							
 meeting during CECON. Texas Section Past Presidents Educational Trust Fund TCEF's Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update. 	2021 Form 990-N v		IRS by CPA Ron Me	eyer on January	17, 2022. Future filings will occur every						
 TCEF's Texas Section Past Presidents Educational Trust Fund Trustees: Jack Furlong PE and Curtis Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.			023 report will be co	mpleted in Augu	st prior to the Fall Board of Direction						
Beitel PE. Current trustees' terms were extended to through 2022 and continuing to identify potential additional trustees to replace term limited members in 2024. • Fund balance as of June 20, 2023 = \$198,436.12 (November 2022 = \$185,695) REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.	Texas Section Pas	st Presidents Ec	lucational Trust Fu	Ind							
REPORT John B. Hawley Memorial Trust Fund Brandon Klenzendorf PE The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update. Volume 4.	Beitel PE. (additional t	Current trustees' rustees to replac	terms were extende e term limited memb	ed to through 202 pers in 2024.	2 and continuing to identify potential						
 The Hawley Fellowship was established in 1961 to promote graduate study and research in hydraulic and environmental engineering. Trustees: Brandon Klenzendorf PhD, PE; Rohit R. Goswami PhD, PE; and Travis Attanasio PE was added for a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update. 				,							
a 2023-2029 term Fund balance as of May 26, 2023 = \$347,544 (was \$312,890 as of September 2022) See investment summary attached. Fellowships: No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.	The Hawley Fellow	ship was establis		note graduate stu							
See investment summary attached. Fellowships : No update. While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status : No update.		Klenzendorf Phl	D, PE; Rohit R. Gos	wami PhD, PE; a	nd Travis Attanasio PE was added for						
While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was opened and no awards distributed. Tax Status: No update.											
	While three to four \$5,000 fellowships were planned to be awarded in 2022, no call for applications was										
Annual Report: 2022 report is in progress.	Annual Report: 20	22 report is in pr	ogress.								

REPORT J. Walter Porter Memorial Trust Fund Ottis Foster PE

The Porter Memorial Fund was established in 1978 to finance periodic fellowships for graduate study and/or research in Water Resources Engineering to individuals who demonstrate outstanding ability and promise of excellence in engineering.

Trustees: Ottis Foster PE, Natalie Guzman PE, Anna Olveda. Mr Foster rolling off soon, see agenda item below.

Fund balance as of as of June 21, 2023 = \$74,626 (March 2023 = \$71,376). See investment summary attached.

The Trustees are working with Edwards Jones investment advisor Kelly Mahmoud to evaluate their fund's investment selections to better accommodate the fund's goal of generating about \$6000 every 2 years.

Fellowship: No update.

A \$5,000 fellowship was awarded in 2022. The trustees plan to award \$5,000 every other year going forward. Trustees will continue to monitor the fund through 2023 to decide if they will proceed with awarding the next \$5,000 scholarship in 2024.

Tax Status: Trustees worked with CPA Ron Meyer to electronically submit a 2022 Form 1041 in April. No balance due nor refund. Considering that 2022 taxable income was \$1,731 at a zero tax rate, Mr Meyer reported that the investment return has been quite effective!

Annual Report: No update.

ITEMS FOR AGENDA

Porter Fund requests the Board begin thinking of a Trustee to replace Ottis Foster, who rolls off in September 2024. The new Trustee should be in or from a career in water resources The new trustee with serve a 6-year term, Oct 2024 through Sept 2030.

Edward **Jones**

MAKING SENSE OF INVESTING

Portfolio for John B Hawley Memorial Trust

Financial Advisor Kelly D. Mahmoud, 512-472-9470 2905 San Gabriel St, Suite 201, Austin, TX 78705 Statement Period Apr 29 - May 26, 2023

Page i of i

AV 02 063278 32649H218 C**5DGT 000000

BRANDON KLENZENDORF & SEAN MERRELL ET AL TTEES U/A DTD 03/04/1985 JOHN B HAWLEY MEMORIAL TRUST 5511 PARKCREST DR SUITE 207 AUSTIN TX 78731-4937



Track your goals on the go

We're here for you even when you're away. Stay connected with your Edward Jones team and your Edward Jones goals and accounts - anytime, anywhere - with our app. Download it from your favorite app store or visit edwardjones.com/app to learn more.

ւրիներինենինիներերերերինըներիներիներներ

Portfolio Summary

Total Portfolio Value

\$347,544.24					
1 Month Ago	\$350,040.74				
1 Year Ago	\$355,584.54				
3 Years Ago	\$307,017.58				
5 Years Ago	\$308,012.13				

Gain a big-picture view

Check the pulse of your overall financial well-being with Online Access by connecting accounts you hold outside Edward Jones. It makes tracking progress toward your goals quick and convenient. Learn more and sign up at edwardjones.com/access.

Overview of Accounts								
Accounts	Account Holder	Account Number	Value 1 Year Ago	Current Value				
Living Trust Select	John B Hawley Memorial Trust	613-25015-1-8	\$2,654.82	\$1,715.14				
Living Trust Guided Solutions Fund Account	John B Hawley Memorial Trust	613-25781-1-0	\$352,929.72	\$345,829.10				
Total Accounts			\$355,584.54	\$347,544.24				

Although account information is provided on this page, it does not guarantee an actual statement was produced. Refer to your account statement for the exact registration and more specific details regarding each account.

Edward Jones®

Edward Jones Online Access - Summary

None of the information provided is intended to replace official account statements.

Holdings for Trust-1								
Current Account Value		Account valu	ie one year ago			Net Change		
\$74,625.59		\$75,233.56				-\$607.97		
Cash								
Description	Current Yield / Rate	Available	Current	Performance Time Frame	Return	Annualized Return	Cost Basis	Unrealized Gain/Loss
Cash		\$4,413.27	\$4,413.27					
	Total:	\$4,413.27	\$4,413.27					

Mutual Funds Held at Edward Jones

Description/ Symbol	Shares	Last Price/ Share	Price \$ Change	Price % Change	Estimated Current Value	Performance Time Frame	Return	Annualized Return	Cost Basis	Unrealized Gain/Loss
AMERICAN BALANCED C (BALCX)	953.471	\$30.06	-\$0.11	-0.36	\$28,661.33	5 yrs 2 mo	\$8,466.08	6.31%	\$25,000.00	\$3,661.34
HARTFORD BALANCED INCOME C (HBLCX)	1814.224	\$13.62	-\$0.04	-0.29	\$24,709.73	5 yrs 2 mo	\$5,540.64	4.32%	\$25,000.00	-\$290.27
HARTFORD CORE EQUITY C (HGICX)	307.192	\$38.59	-\$0.19	-0.49	\$11,854.53	4 yrs 3 mo	\$4,303.71	10.40%	\$8,500.00	\$3,354.54

Member SIPC. The information provided in this document can include assets held at Edward Jones and other institutions. Edward Jones does not verify the value, ownership or SIPC coverage of all assets held at other institutions. None of the information provided in this document is intended to replace official documents such as transaction confirmations and account statements from any institution. Explanations about the calculations and presentation of information, as well as additional important disclosures, can be found at edwardjones.com/en_US/disclosures/online_account/display_account_info/index.html.

Edward Jones[®]

MFS INTL DIVERSIFICATION C (MDIGX)	233.025	\$21.40	-\$0.34	-1.56	\$4,986.73	3 yrs 6 mo	\$486.74	2.97%	\$4,808.95	\$177.79
				Total:	\$70,212.32				\$63,308.95†	\$6,903.40†
*Previous business day										

Total:

\$74.625.59

† Total Cost Basis and Total Unrealized Gain/Loss do not include values for positions missing cost basis information or for Money Market Funds.

Total Cost basis and total official documents should not be relied upon for tax preparation purposes. Cost basis information may be from outside sources and has not been verified for accuracy. Refer to your official tax documents for information about reporting cost basis. Consult a qualified tax advisor or an attorney regarding your situation. If you believe the cost basis information provided in this document can include assets held at Edward Jones and other institutions. Edward Jones does not verify the value, ownership or SIPC coverage of all assets held at other institutions. None of the information provided in this document is intended to replace official documents such as transaction confirmations and account statements from any institution. Explanations about the calculations and presentation of information, as well as additional important disclosures,

can be found at edwardjones.com/en_US/disclosures/online_account/display_account_info/index.html.